

A.S.S. REC-33Y: TaujuaREF: CS/ASM 2204466/TgY3ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 3280K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMZ 6736EYr Regn: 2021 MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Alphardc.c. 2493Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 24330

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AGH 300367-522Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 17/5/22Survey held at XinyunDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

Rep. Form: _____

Lum Sum / L.B. / P. _____



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ6736Z 2022 Alphard PI

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	1244 \$ 1,517.30 de -
2	1	Rear bumper left bracket	\$ 98.00 cua -
3	1	Rear bumper right bracket	\$ 98.00 X un
4	1	Rear left side retainer	\$ 95.00 Cu -
5	1	Rear right side retainer	\$ 95.00 X un
3	1	Rear bumper tow cover	\$ 68.00 de -
5	1	Bumper refector left	110 \$ 225.00 Cu -
6	1	Bumper refector right	\$ 225.00 X un
7	1	Rear left side cover trim-side guard cover	\$ 283.50 de -
8	1	Bumper lower side trim	\$ 168.30 de -
9	1	Lower cover trim	\$ 228.50 X un
10	1	Sensor cable	\$ 850.00 X un
11	2	Sensor with bracket at left and middle	\$ 600.00 un - 400
12	1	Lower tray at left area	\$ 285.00 X un
13	1	Tailgate	\$ 2,200.00 R X
14	1	Tailgate rubber	\$ 280.00 X un
15	1	Rear end panel / side panel	\$ 950.00 Ry
16	1	Reinforcement / side support metal	450 \$ 550.00 bt
17	1	Alphard logo	\$ 105.00 de -
18	1	Toyota logo	\$ 95.00 de -
19	1	Rear left light	\$ 1,800.00 X un
20	1	Rear tailgate light	\$ 1,500.00 X un
		Parts sub-total	\$ 12,316.60

3116.80
25% - 2337.60



Xin Yun Auto Private Limited


辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMZ6736Z 2022 Alphard PI

No	Qty	Parts Description	Estimated Parts Price
		<u>Special Nett Items</u>	
1	10	Rear bumper clips	\$ 100.00 30 net ✓
2	8	Rear side bracket clips square clips	\$ 80.00 to
3	8	Rear end lower panel top garnish clips	\$ 80.00 X
4	1	Rear side panel sealant	\$ 120.00 X
5	8	Rear side trim clips	\$ 80.00 X
6	6	Tailgate garnish clips	\$ 80.00 X
7	10	Rear lower trim clips	\$ 60.00 X
8	1	Rear no plate with garnish	\$ 80.00 X
		Sub total special nett	\$ 680.00 20



No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area	\$ 2,000.00 500
2	To putty and spray painting behind portion.	\$ 2,000.00 600
3	To check wiring and focus behind lights	\$ 80.00 30 X
4	To apply anti rust proofing to front affected area.	\$ 200.00 30
5	To remove and install undercarriage parts.	\$ 150.00 X nn
6	To balance the wheel.	\$ 80.00 X nn
7	To conduct wheel alignment.	\$ 120.00 X nn
8	Ceremic coating for affected area	\$ 150.00 Run
9	Remove and install winscreen facillite works	\$ 150.00 nrx
10	Rear water test	\$ 120.00 X nn
11	Remove and install tailgate internal and side trims and light	\$ 250.00 60
12	Check rear bumper wiring	\$ 100.00 30
13	Computer reset system / after accident	\$ 250.00 X nn
Total repair cost :		5,650.00

Tanp'kin 97495749
 WP 17/5/22 C1/Jan
 L/S Bony after repair
 Tanp'kin C. 1/haunt in
 04 days

2337.60
 30
 1220
 3587.60
 1/58 2850
 04 days
 *

LEK Auto-Consultants hence notify the Repaire of the following:

- To purchase the necessary parts
- To display damaged parts during survey
- Part list is to be signed by customer
- Third party survey is to be carried out on a non-basis
- Adequate insurance cover
- Supreme panel must be approved by Insurance Company

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: