

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 2552D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED / CRACKED	1,480.21	1,251.00
1	REAR BUMPER LOWER (CONSISTENT)	DEFORMED	1,120.50	645.00
1	REAR BUMPER REFLECTOR LAMP O/S (CONSISTENT)	CRACKED	845.10	620.10
1	REAR BUMPER CHROME MOULDING CENTRE (CONSISTENT)	SCRATCHED	488.20	399.00
2	REAR BUMPER CHROME SIDE MOULDINGS @\$360.00 (CONSISTENT)	NECESSARY	720.00	500.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER PDC SENSOR (CONSISTENT)	SERVICEABLE	345.10	-
1	REAR BUMPER SPONGE (CONSISTENT)	CRACKED	168.10	168.10
1	REAR BUMPER BEAM (CONSISTENT)	DENTED	799.20	755.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	866.50	-
	LESS 25% DISCOUNT		-	-1,097.05
			6,882.91	3,291.15
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	20.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO RESET & DIAGNOSTIC SYSTEM.		180.00	80.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY .	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL		680.00	300.00
	TO PUTTY & SPRAY PAINTING.		850.00	400.00
			2,040.00	850.00
	GRAND TOTAL		8,922.91	4,141.15



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,300.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM22004467/Uea3q2

CHUA KANG SENG
Licensed Appraiser