

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE Code: ASM Policy Particulars:- THIRD PARTY CLAIM Insured Veh. SHD 378U Ref: CC4/ASM22004 Date: 18/08/2022 Code: ASM Veh. Inspected SKE 2552D	4467/Uea3q2
AXA TOWERSINGAPORE 068811 ATTN: YVONNE Code: ASM 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SHD 378U Veh. Inspected SKE 2552D	
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SHD 378U Veh. Inspected SKE 2552D	
Insured Veh. SHD 378U Veh. Inspected SKE 2552D	
Policy No. P2459880 Coverage (\$) 0.00	
Claim No. S2M040R5 Excess (\$) 0.00	
Assign From Assign Date 12/05/2022	
2. Vehicle Particulars & Condition	
Make & Model TOYOTA HARRIER HYBRID (A) c.c 2487	
Engine No. HIDDEN Year of Reg. 2021	
Chassis No. JTEAD3BHX0J000655 Colour WHITE	
Odometer 9915 KM Steering IN ORDER	
Brakes IN ORDER Modification SPORTS RIM	
General GOOD	
3. Conditions of Tyres	
Size Make Balance	
R/H Front Tyre 225/60 R18 BRIDGESTONE 9 mm	
L/H Front Tyre 225/60 R18 BRIDGESTONE 9 mm	
R/H Rear Tyre 225/60 R18 BRIDGESTONE 9 mm	
L/H Rear Tyre 225/60 R18 BRIDGESTONE 9 mm	
4. Description of Damages	
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.	
DAMAGES SEE DETAILS.	
5. General Information	
Accident Date 11/05/2022 Inspection Date 12/05/2022	
Survey held at FASTECH AUTO PTE LTD	
1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883	
5a. Remarks	
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
5b. Estimate Days of Repair	
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	