

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM 2200 4467/423

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKE2552D

at Workshop m/s

f1

of

Insured:

SHD 3784

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

170k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

945, Vehicle: IN / OUT
21A 20230

Date / Time

Action / Instruction

Dep 17k.

28/5/22 4/5 have G.A
\$3300 informed A/cn.

Veh No:

SKE2552D

Yr Regn:

28/07/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A) Hybrid

Make:

Toyota harrier

C.C

2487

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

9915

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTEAD3BH X0J000655

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/5/22

D.O.I.

12/5/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Ashur

not Authorized
dealer

12/5/22

2/53300/
3 day

VEHICLE No: SKE 2552D

1PC	REAR BUMPER	De/cnr	1257.00	\$1,480.21	/
1PC	REAR BUMPER LOWER	De	645.00	\$1,120.50	/
1PC	REAR BUMPER REFLECTOR LAMP O/S	one	620.10	\$845.10	/
1PC	REAR BUMPER CHROME MOULDING CENTRE	scr	399.00	\$488.20	/
2[CS	REAR BUMPER CHROME SIDE MOULDINGS @\$360.00	one	250x2=500	\$720.00	/
1SET	REAR BUMPER CLIPS	one		\$50.00	/
1PC	REAR BUMPER PDC SENSOR	suc		\$345.10	X
1PC	REAR BUMPER SPONGE	cm		\$168.10	/
1PC	REAR BUMPER BEAM	10	65% 75%	\$799.20	/
1PC	REAR END PANEL	R		\$866.50	X
				\$6,882.91	

TO CHECK WIRING

\$50.00 20

TO DISMANTLE & REPLACED REAR PDC SENSOR

\$80.00 50

TO RESET & DIAGNOSTIC SYSTEM

\$180.00 80

TO DISMANTLE & REFIX CUSHION UPHOLSTERY

11 \$120.00 X

TO SPRAY RUST PROOFING

11 \$80.00 X

LABOUR FOR PANEL BEATING & REPLACED PARTS

\$680.00 300

TO PUTTY & SPRAY PAINTING

\$850.00 400

TOTAL \$8,922.91

2-4388.20

257

9-3291.15

1-850

4141.15

292

3312

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: