

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004472/KVY3Q2**Date:** 30/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00002192200

Claimant Vehicle No : SKX7680J **Insured Vehicle No :** PC4563K

Date of Loss: 10/05/2022 Nature of Claim: TP Claim No: SNM22D203212/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX7680J**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UGR9051

Reg. Date: 24/07/2018 (Man. Year: 2018) Chassis No: MMBSTA13AJH001698

Colour: Metallic Blue Odometer: 47018 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,951.00	3,786.00	1,165.00	23.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	3,280.00	400.00	10.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,631.00	7,066.00	1,565.00	18.13
+ GST 7.00/7.00% (S\$)	604.17	494.62	109.55	18.13
Nett Amount (S\$)	9,235.17	7,560.62	1,674.55	18.13

INSPECTION

Date of Assignment: 11/05/2022

Date Inspected: 12/05/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Dec 2022)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX7680J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	250.00 F	*250.00 F
2	1		*REAR BUMPER LOWER PROTECTOR	Cracked	450.00 F	*450.00 F
3	1		*REAR BUMPER SIDE RETAINER RH	Cracked	15.00 F	*15.00 F
4	1		*REAR BUMPER INNER GARNISH RH	Serviceable	12.00 F	*- F
5	6		*REAR BUMPER CLIP	Necessary	12.00 F	*12.00 F
6	1		*REAR BUMPER CENTRE INNER GARNISH	Serviceable	45.00 F	*- F
7	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	480.00 F	*- F
8	1		*REAR BOOT	Bent	380.00 F	*380.00 F
9	1		*REAR BOOT LOGO	Necessary	28.00 F	*28.00 F
10	1		*REAR BOOT EMBLEM -ATTRAGE	Necessary	18.00 F	*18.00 F
11	1		*REAR BOOT EMBLEM -MIVEC	Necessary	42.00 F	*42.00 F
12	1		*REAR BOOT INNER LOCK	Dented	100.00 F	*100.00 F
13	1		*REAR BOOT INNER RUBBER	Distorted	68.00 F	*68.00 F
14	1		*REAR BOOT OUTER MOULDING	Dented	175.00 F	*175.00 F
15	1		*REAR BOOT HINGE LH	Bent	90.00 F	*90.00 F
16	1		*TAILLAMP	N/S Broken / O/S Serviceable	256.00 F	*128.00 F
17	1		*TAILLAMP PANEL LH	Bent	55.00 F	*55.00 F
18	1		*REAR CENTRE PANEL	Bent	220.00 F	*220.00 F
19	1		*REAR CENTRE PANEL INNER TOP GARNISH	Dented	45.00 F	*45.00 F
20	1		*REAR SPARE TYRE TOP BOARD	Cracked	105.00 F	*105.00 F
21	1		*REAR SMART KEY SENSOR	Dented	65.00 F	*65.00 F
22	1		*REAR LH FENDER	Buckled	460.00 F	*460.00 F
23	1		*REAR LH FENDER INNER SHIELD	Cracked	24.00 F	*24.00 F
24	1		*REAR LH FENDER INNER GARNISH	Deformed	118.00 F	*118.00 F
25	1		*REAR SPARE TYRE COMPARTMENT	Repair	500.00 F	*- F
26	1		*REAR BOOT TOP GARNISH SPOILER	Cracked	280.00 FS	*280.00 FS
27	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
28	1		*SET REVERSE CAMERA	Dented	350.00 FS	*350.00 FS
29	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
30	1		*BUZZER SENSOR	Cracked	68.00 F	*68.00 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,951.00** **3,786.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	100.00	100.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,REAR BOOT & ATTACHMENT .TO CUT,WELD & RENEW REAR LH FENDER ,REAR PANEL ,REAR COMPARTMENT ,LH TAILLAMP PANEL ,TO STRAIGHTEN ,KNOCK & REPAIR REAR LH CHASSIS ,REAR FENDER INNER PANEL & REALIGN THE SAME	New	1,800.00	1,500.00
3	REMOVE & REFIX SEAT ,CARPET ,GARNISH ,TOP ROOF LINING ,ETC	New	100.00	100.00
4	PUTTY & RESPRAY ON REAR COMPARTMENT ,REAR BOTH FENDERS ,REAR PANEL ,TAILLAMP PANEL ,BOOT ,HINGES ,REAR BUMPER ,SPOILER AND LOWER SKIRT	New	1,500.00	1,400.00
5	RUSTPROOFING	New	100.00	100.00
6	REAR COMPARTMENT PANEL TOP COAT	New	80.00	80.00
7	TOWING BY OWNER (NPA)	New	0.00	0.00
Gross Labour Cost (S\$)			3,680.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >