

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004481/KPA3Q2**Date:** 08/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100095990-13
Claimant Vehicle No :	SHB5105T	Insured Vehicle No :	SJJ5330T
Date of Loss:	07/05/2022	Nature of Claim:	TP
		Claim No:	5867866809SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5105T		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR8262958
Reg. Date:	19/12/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU403576929
Colour:	Metallic Brown	Odometer:	457618 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 7 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 7 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,155.40	0.00	4,155.40	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,992.00	400.00	1,592.00	79.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	6,147.40	400.00	5,747.40	93.49
+ Loss of Use (3.0 x S\$50.00/day) (\$\$)		150.00		
+ Car Rental (3.0 x S\$70.00/day) (\$\$)		210.00		
+ Doc/Search Fee (\$\$)		7.00		
Nett Liability (\$\$)		767.00		
Global Sum Settlement (\$\$)		760.00		

INSPECTION

Date of Assignment:	10/05/2022	
Date Inspected:	10/05/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
2	2		*PAD,RR BUMPER RH & LH,1	Not Necessary	7.60 F	*- F
3	2		*PAD,RR BUMPER RH & LH,2	Not Necessary	7.60 F	*- F
4	2		*PAD,RR BUMPER RH & LH,3	Not Necessary	7.60 F	*- F
5	3		*PAD,RR BUMPER CTR	Not Necessary	6.60 F	*- F
6	2		*STOPPER,RR BUMPER,RH & LH	Not Necessary	8.60 F	*- F
7	2		*SEAL,RR BUMPER ARM,RH & LH	Not Necessary	22.00 F	*- F
8	1		*RETAINER,RR BUMPER,LH	Not Necessary	111.50 F	*- F
9	1		*SEAL,RR BUMPER,LH	Not Necessary	85.20 F	*- F
10	10		*CLIPS,PIECE,FRT & RR BUMPER	Not Necessary	15.00 F	*- F
11	1		*GUARD,RR BUMPER LOWER	Not Necessary	558.30 F	*- F
12	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
13	1		*ANTENNA,ELECTRICAL KEY	Not Necessary	60.30 F	*- F
14	1		*LENS & BODY ASSY,RR BUMPER,LH	Not Necessary	486.80 F	*- F
15	1		*LENS & BODY REAR COMBINATION LAMP,LH	Not Necessary	438.10 F	*- F
16	1		*COVER,REAR FLOOR UNDER,LH	Not Necessary	234.30 F	*- F
17	1		*COVER,REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
18	1		*PANEL SUB-ASSY,FENDER REAR LH	Not Necessary	824.80 F	*- F
19	1		*LINER,REAR FENDER,LH	Not Necessary	135.80 F	*- F
20	1		*COVER,RR BUMPER ASSY	Repair	423.90 F	*- F

F=Franchise part.

Total Parts (\$\$)	4,155.40	0.00
---------------------------	-----------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	200.00
2	SPRAY PAINT	New	936.00	200.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
Gross Labour Cost (\$\$)			1,992.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >