

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004482/EQY3M4**Date:** 02/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00002412201

Claimant Vehicle No : SND655Z **Insured Vehicle No :** SLK8445Y

Date of Loss: 10/05/2022 Nature of Claim: TP Claim No: SNM22D203206/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SND655Z**

Make & Model: TOYOTA COROLLA ALTIS, 1.8 E HYBRID ELEGANCE (2WD) (A) Engine No: 2ZRY789852

Reg. Date: 01/12/2021 (Man. Year: 2021) Chassis No: MR2BZ3BE400008667

Colour: Grey Odometer: 55007 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,494.25	5,889.35	8,604.90	59.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,860.00	1,840.00	39.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,194.25	8,749.35	10,444.90	54.42
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	19,194.25	7,000.00	12,194.25	63.53
+ GST 7.00/7.00% (S\$)	1,343.60	490.00	853.60	63.53
Nett Amount (S\$)	20,537.85	7,490.00	13,047.85	63.53

INSPECTION

Date of Assignment: 12/05/2022

Date Inspected: 13/05/2022 Inspected At: MY CAR CONSULTANT PTE LTD (HQ)
60 JALAN LAM HUAT
#05-21 CARROS CENTRE
SINGAPORE 737869

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Jun 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.8 E HYBRID ELEGANCE (2WD) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SND655Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,024.00 FL	*856.00 FL
2	1		*BOOTLID INNER TRIM	Crushed	359.00 FL	*278.00 FL
3	4		*BOOTLID STOPPER	Not Necessary	300.00 FL	*- FL
4	1		*BOOTLID TOP LOCK	Bent	398.00 FL	*256.00 FL
5	1		*BOOTLID TOP LOCK COVER	Not Necessary	68.00 FL	*- FL
6	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	312.00 FL	*- FL
7	1		*BOOTLID LOWER LOCK	Not Necessary	39.00 FL	*- FL
8	1		*BOOTLID WEATHER STRIP	Crushed	220.00 FL	*207.00 FL
9	1		*BOOTLID LOGO	Necessary	74.00 FL	*68.00 FL
10	1		*BOOTLID EMBLEM ALTIS	Necessary	65.00 FL	*50.00 FL
11	1		*BOOTLID SENSOR (ANTENNA)	Broken	312.00 FL	*280.00 FL
12	1		*BOOTLID EMBLEM COROLLA	Necessary	65.00 FL	*50.00 FL
13	2		*BOOTLID NUMBER PLATE LAMP	Not Necessary	124.00 FL	*- FL
14	1		*REAR BUMPER	Broken	698.00 FL	*581.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Broken	224.00 FL	*200.00 FL
16	2		*REAR BUMPER BRACKET	Not Necessary	326.00 FL	*- FL
17	1		*REAR BUMPER SENSOR (2PCS)	Broken (1pc only)	762.00 FL	*200.00 FL
18	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	587.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Dented	395.00 FL	*332.70 FL
20	1		*REAR BUMPER UNDERCOVER CENTRE	Broken	315.00 FL	*315.00 FL
21	1		*REAR BUMPER UNDERCOVER LH	Not Necessary	215.00 FL	*- FL
22	1		*REAR BUMPER UNDERCOVER RH	Not Necessary	236.00 FL	*- FL
23	1		*AIR VANT	Not Necessary	65.00 FL	*- FL
24	2		*REAR FENDER	Repair	2,048.00 FL	*- FL
25	2		*REAR FENDER COWLING	Not Necessary	716.00 FL	*- FL
26	1		*REAR WINDSCREEN MOULDING	Not Necessary	112.00 FL	*- FL
27	1		*REAR END PANEL	Dented	695.00 FL	*617.00 FL
28	1		*END PANEL TOP GARNISH	Crushed	278.00 FL	*278.00 FL
29	1		*REAR FLOOR PANEL	Dented	1,025.00 FL	*937.00 FL
30	1		*REAR SPARE TYRE TOP BOARD	Crushed	357.00 FL	*291.80 FL
31	1		*REAR EXHAUST PIPE	Not Necessary	951.00 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	398.00 FL	*- FL
33	2		*REAR EXHAUST MOUNTING	Not Necessary	56.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
35	1		*BOOTLID INSULATOR CLIPS	Necessary	30.00 FS	*20.00 FS
36	1		*BOOTLID STICKER	Necessary	50.00 FS	*30.00 FS
37	1		*TAILAMP CLIPS SET	Not Necessary	40.00 FS	*- FS
38	1		*REAR FENDER SEALANT	Not Necessary	150.00 FS	*- FS
39	1		*REAR FENDER COWLING CLIPS SET	Not Necessary	50.00 FS	*- FS
40	1		*REAR FENDER INNER TRIM CLIPS SET	Necessary	50.00 FS	*20.00 FS
41	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
42	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
43	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
44	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*30.00 FS
45	1		*REAR SPARE TYRE PANEL SEALANT	Necessary	150.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

6/2/22, 6:26 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REVERSE CAMERA	Not Necessary	400.00 FS	*- FS
47	1		*TAILAMP C/W CHROME	O/s Broken	1,224.00 FL	*612.00 FL
48	1		*TAILAMP LOWER PANEL	O/s Dented	644.00 FL	*322.00 FL
49	1		*REAR BUMPER REFLECTOR	O/s Broken	224.00 FL	*59.30 FL
50	1		*REAR FENDER INNER TRIM	O/s Crushed	796.00 FL	*379.00 FL
51	1		*BOOTLID REFLECTOR C/W CHROME	O/s Cut	912.00 FL	*456.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					18,899.00	7,795.80
- List Item Discount on L Items 25.00/25.00% (S\$)					4,404.75	1,906.45
Total Parts (S\$)					14,494.25	5,889.35
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON AFFECTED AREAS.	New	1,600.00	1,200.00
2	PANEL BEATING ON AFFECTED AREAS.	New	2,200.00	1,400.00
3	REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	150.00	0.00
4	REMOVE AND REFIX REAR BOOTLID MECHANISM.	New	100.00	80.00
5	REMOVE AND REFIX REAR EXHAUST SYSTEM.	New	150.00	80.00
6	REMOVE AND REFIX FUEL TANK ASSY.	New	150.00	0.00
7	REAR CHASSIS ALIGNMENT.	New	200.00	0.00
8	TO CHECK ELECTRICAL WIRING.	New	100.00	50.00
9	APPLY ANTI RUST ON AFFECTED AREAS.	New	50.00	50.00
Gross Labour Cost (\$)			4,700.00	2,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >