

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004484/KPA3Q2**Date:** 13/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210039386
Claimant Vehicle No :	SHF35Z	Insured Vehicle No :	GBL2613G
Date of Loss:	08/05/2022	Nature of Claim:	TP
		Claim No:	6320207907SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF35Z		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2G94396
Reg. Date:	01/12/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU303091987
Colour:	Metallic Brown	Odometer:	122639 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 8 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,548.80	1,341.24	15,207.56	91.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,404.00	1,700.00	3,704.00	68.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	21,952.80	3,041.24	18,911.56	86.15
+ Loss of Use (7.0 x S\$70.00/day) (S\$)		490.00		
+ Car Rental (7.0 x S\$73.00/day) (S\$)		511.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		4,049.24		
Global Sum Settlement (S\$)		4,000.00		

INSPECTION

Date of Assignment:	10/05/2022	
Date Inspected:	10/05/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REINFORCEMENT (DISC 25%)	Bent	332.70 F	*249.53 F
2	1		*COVER,RR BUMPER ASSY (DISC 25%)	Bent	485.60 F	*364.20 F
3	2		*PAD,RR BUMPER,RH & LH 3 (DISC 25%)	Necessary	22.00 F	*16.50 F
4	2		*PAD,RR BUMPER,RH & LH 2 (DISC 25%)	Necessary	8.00 F	*6.00 F
5	2		*PAD,RR BUMPER,RH & LH 1 (DISC 25%)	Necessary	8.00 F	*6.00 F
6	3		*PAD,RR BUMPER,CTR (DISC 25%)	Necessary	33.00 F	*24.75 F
7	1		*SEAL RR BUMPER ARM,RH & LH (DISC 25%) (2 Pcs)	Necessary	22.60 F	*16.95 F
8	1		*RETAINER,RR BUMPER,RH (DISC 25%)	Distorted	132.60 F	*99.45 F
9	1		*CLIPS PIECE,FRT & RR BUMPER (DISC 25%) (10 Pcs)	Necessary	45.00 F	*33.75 F
10	1		*GUARD,RR BUMPER,LOWER (DISC 25%)	Buckled	374.50 F	*280.88 F
11	1		*COVER,GUARD RR BUMPER LOWER (DISC 25%)	Missing	22.00 F	*16.50 F
12	1		*REAR BUMPER REFLECTOR ASSY,REFLEX RH (DISC 25%)	Cracked	39.00 F	*29.25 F
13	1		*NAME PLATE (HYBRID) LUGGAGE COMPARTMENT	Necessary	54.60 F	*40.95 F
14	1		*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	47.90 F	*35.93 F
15	1		*NAME PLATE (PRIUS) LUGGAGE COMPARTMENT	Necessary	54.60 F	*40.95 F
16	1		*DUCT ASSY,QUARTER VENT RH & LH (DISC 25%)	Necessary	67.00 F	*50.25 F
17	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
18	1		*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F
19	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
20	2		*STOPPER,RR BUMPER,RH & LH	Not Necessary	4.50 F	*- F
21	1		*RETAINER,RR BUMPER,LH	Not Necessary	132.60 F	*- F
22	1		*SEAL,RR BUMPER,RH	Not Necessary	118.30 F	*- F
23	1		*SEAL,RR BUMPER,LH	Not Necessary	118.30 F	*- F
24	1		*REAR BUMPER REFLECTOR ASSY,REFLEX,LH	Not Necessary	39.00 F	*- F
25	1		*REAR BUMPER GROMMET SCREW	Not Necessary	2.20 F	*- F
26	1		*COVER,REAR FLOOR UNDER,LH	Not Necessary	241.90 F	*- F
27	1		*COVER,REAR FLOOR UNDER CENTER	Not Necessary	229.90 F	*- F
28	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Not Necessary	339.60 F	*- F
29	1		*LENS & BODY,REAR COMBINATION LAMP,LH	Not Necessary	339.60 F	*- F
30	1		*COVER,REAR COMBINATION LAMP,RH	Not Necessary	69.90 F	*- F
31	1		*COVER,REAR COMBINATION LAMP,LH	Not Necessary	69.90 F	*- F
32	1		*SOCKET & WIRE SUB-ASSY,REAR COMBINATION LAMP	Not Necessary	52.30 F	*- F
33	1		*LENS & BODY,REAR COMBINATION LAMP,NO 2	Not Necessary	261.00 F	*- F
34	1		*LAMP ASSY,REAR RH	Not Necessary	293.60 F	*- F
35	1		*LAMP ASSY,REAR LH	Not Necessary	293.60 F	*- F
36	1		*ANTENNA,ELECTRICAL KEY	Not Necessary	72.00 F	*- F
37	1		*MEMBER SUB-ASSY,RAIL ROOT SIDE REAR RH	Not Necessary	288.50 F	*- F
38	1		*PANEL SUB-ASSY,FENDER REAR RH	Not Necessary	871.50 F	*- F
39	2		*PATCH,SIDE PANEL REAR END,RH & LH	Not Necessary	33.70 F	*- F
40	1		*LINER,REAR FENDER,RH	Not Necessary	139.80 F	*- F
41	1		*END PANEL SUB-ASSY,BODY LOWER BACK	Not Necessary	651.00 F	*- F
42	1		*TAIL GATE PANEL SUB-ASSY,BACK DOOR	Not Necessary	1,147.80 F	*- F
43	1		*TAIL GATE CUSHION,BACK DOOR LOWER STOPPER	Not Necessary	23.70 F	*- F
44	1		*TAIL GATE GLASS SUB-ASSY,BACK DOOR	Not Necessary	1,656.70 F	*- F
45	1		*TAIL GATE MOULDING GLASS,BACK DOOR	Not Necessary	35.50 F	*- F
46	1		*TAIL GATE LOWER GLASS SUB-ASSY,BACK DOOR	Not Necessary	761.40 F	*- F
47	1		*TAIL GATE BACK DOOR HINGE ASSY,LH	Not Necessary	61.00 F	*- F
48	1		*TAIL GATE BACK DOOR HINGE ASSY,LH	Not Necessary	61.00 F	*- F
49	1		*TAIL GATE LOCK ASSY,BACK DOOR	Not Necessary	467.00 F	*- F
50	1		*TAIL GATE LOCK COVER,BACK DOOR	Not Necessary	30.20 F	*- F
51	1		*AUTO TAILGATE SYSTEM	Not Necessary	2,520.00 F	*- F
52	1		*EMBLEM SIDE PANEL (HYBRID)	Not Necessary	54.60 F	*- F
53	1		*MOULDING SUB-ASSY ROOF TOP	Not Necessary	656.90 F	*- F
54	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Not Necessary	913.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*COVER,TAIL GATE BACK DOOR GARNISH	Not Necessary	8.50 F	*- F
56	1		*COVER,REAR FLOOR UNDER,RH	Serviceable	175.10 F	*- F
57	1		*LENS & BODY,REAR COMBINATION LAMP,NO 2	Serviceable	261.00 F	*- F
58	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	Repair	913.60 F	*- F
59	1		*REVERSE SENSOR	Not Necessary	180.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					16,548.80	1,341.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,952.00	780.00
2	SPRAY PAINT	New	2,612.00	850.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	0.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	50.00
8	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$\$)			5,404.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >