

ASS. REC. BY:

REF:

REF: A61

DDR4

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.0.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

S14F 352

Yr Regn:

12.20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c.

1790

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

122639

T/Radio:

Insured / Std / NI / NA

Eng/No:

30

C/No:

J70KB3Fu3091987

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD / ARlm or

Tyre Size:

F: Falken

195/65R15

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

S

mm

R/Bal.

3

mm

L/Bal.

S

mm

L/Bal.

3

mm

D.O.A.

8/5/22

D.O.I.

10/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Case Details

Case Reference Number : TAX05222017
Type of Repair : Accident Repair
Vehicle Registration Number : SHF352

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-182314D
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 08/05/2022 02:55 PM
Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	1	249.52	Replace	✓
Standard	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	✓
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓
Standard	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	✓
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	2	16.95	Replace	✓
Standard	Main			STOPPER, RR BUMPER, RH & LH	1	4.50	4.50	25.00	3.38	Replace	0	0	Not Give	✓
Standard	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	1	99.45	Replace	✓
Standard	Main			RETAINER, RR BUMPER, LH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	✓
Standard	Main			SEAL, RR BUMPER, RH	1	118.30	118.30	25.00	88.73	Replace	0	0	Not Give	✓
Standard	Main			SEAL, RR BUMPER, LH	1	118.30	118.30	25.00	88.73	Replace	0	0	Not Give	✓
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓
Standard	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	✓

Total Spare Part Cost 13,195.38

Lump Sum Discount (%) 0.00

Final Spare Part Cost 13,195.38

Surveyor Total 1,290.97

Lump Sum Dis (%) 0

Final Sur Total 1,290.97

REF: /TJM/ 72

SOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	1	16.50	Replace	▼
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	1	29.25	Replace	▼
Standard	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	39.00	39.00	25.00	29.25	Replace	0	0	Not Give	▼
Standard	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.33	Replace	0	0	Check	▼
Standard	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Not Give	▼
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	▼
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	▼
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	▼
Standard	Main			SOCKET & WIRE SUB-ASSY, REAR COMBINATION LAMP, RH	1	52.30	52.30	10.00	47.07	Replace	0	0	Not Give	▼
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	261.00	261.00	10.00	234.90	Replace	0	0	Check	▼
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	1	261.00	261.00	10.00	234.90	Replace	0	0	Not Give	▼
Standard	Main			LAMP ASSY, REAR, RH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	▼
Standard	Main			LAMP ASSY, REAR, LH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	▼
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	▼
Standard	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Not Give	▼

Total Spare Part Cost 13,195.38

Surveyor Total 1,290.97

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 13,195.38

Final Sur Total 1,290.97

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation					Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)					Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			MEMBER SUB-ASSY, RAIL ROOT SIDE REAR RH	1	288.50	288.50	25.00	216.38	Replace	0	0	0	Not Give	✓
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	871.50	871.50	25.00	653.63	Replace	0	0	0	Not Give	✓
Standard	Main			PATCH, SIDE PANEL REAR END, RH & LH	1	33.70	33.70	25.00	25.28	Replace	0	0	0	Not Give	✓
Standard	Main			LINER, REAR FENDER, RH	1	139.80	139.80	25.00	104.85	Replace	0	0	0	Not Give	✓
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	1,147.80	1,147.80	25.00	860.85	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE CUSHION, BACK DOOR LOWER STOPPER	1	23.70	23.70	25.00	17.78	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,656.70	1,656.70	25.00	1,242.53	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	35.50	35.50	25.00	26.63	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	761.40	761.40	25.00	571.05	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	1	0	0	Repair	✓
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	61.00	61.00	25.00	45.75	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, LH	1	61.00	61.00	25.00	45.75	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	467.00	467.00	10.00	420.30	Replace	0	0	0	Not Give	✓
Standard	Main			TAIL GATE LOCK COVER, BACK DOOR	1	30.20	30.20	25.00	22.65	Replace	0	0	0	Not Give	✓
Standard	Main			AUTO TAILGATE SYSTEM	1	2,520.00	2,520.00	10.00	2,268.00	Replace	0	0	0	Not Give	✓
Standard	Main			EMBLEM, SIDE PANEL (HYBRID)	1	54.60	54.60	25.00	40.95	Replace	0	0	0	Not Give	✓
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	1	40.95	40.95	Replace	✓

Total Spare Part Cost 13,195.38

Surveyor Total 1,290.97

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 13,195.38

Final Sur Total 1,290.97

Line	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks	
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			EMBLEM SUB-ASSY REAR	1	47.90	47.90	25.00	35.93	Replace	1	35.92	Replace	▼	
Standard	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	1	40.95	Replace	▼	
Standard	Main			MOULDING SUB-ASSY, ROOF TOP	1	656.90	656.90	25.00	492.67	Replace	0	0	Not Give	▼	
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	0	0	Not Give	▼	
Standard	Main			COVER, TAIL GATE BACK DOOR GARNISH	1	8.50	8.50	25.00	6.38	Replace	0	0	Not Give	▼	
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	▼	
Standard	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	▼	
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	▼	
Total Spare Part Cost									13,195.38	Surveyor Total		1,290.97			
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		0			
Final Spare Part Cost									13,195.38	Final Sur Total		1,290.97			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION RH	1,352.00	300	
Total:			1,352.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FLOOR CORNER PANEL RH	180.00	0	
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	150	
4	Main	TO RESPRAY TAIL GATE	378.00	0	
5	Main	TO RESPRAY REAR FENDER RH	378.00	0	
6	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,854.00	350.00	

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:		1,854.00	350.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50	
6	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			840.00	70.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	13,195.38	1,290.97
Total Labour Cost	1,352.00	300.00
Total Spray Painting	1,854.00	350.00
Other	840.00	70.00
Overall Total	17,241.38	2,010.97
Lump Sum Repair Option		☐
Lump Sum Total	0.00	2,010.97
Surveyor Approved Amount		2,010.97
No of Repair Days*	8	3
Remarks	-	PART BY PART REPAIR / BEFORE PAINT PHOTO / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email Kenneth Kong (LKK)
Surveyor Name		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ASSIGNMENT 11.17

Kenner

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/05/2022 16:12 (SGT)
Date of Accident	08/05/2022 22:55 (SGT)
Exact Location of Accident	Ang Mo Kio Ave 1, Singapore
Additional Location Information	SLIP ROAD FROM ANG MO KIO AVE 6 TOWARDS AVE 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF35Z
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-22099115MFSH
Cover Note Number	-

DRIVER

Name of Driver	TEO AIK KIAT (ZHANG YUJIE)
NRIC No	SXXXX707H

Hand-drawn diagram of a car accident scene. A car labeled 'A' is on the left, and a car labeled 'B' is on the right. An arrow labeled 'Taxi (A)' points towards car A. An arrow labeled 'Van (B)' points towards car B. The text 'GBL 26136' is written on the right side, and 'SHF 352' is written below it.

[illegible]

We declare the foregoing particulars are true in every respect.



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

2/22/22 09/05/2022