

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

PRE-REPAIR INSPECTION REPORT

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22004487/Gpa3e2
	300 BEACH ROAD			Date:	30/05/2022
	#17-04/07 THE CO	NCOURSESINGAPORE 199555		Cada	L DC2
4		Dell'es Deut'estess	/TURE BART	Code:	
1.	, , ,				
	Insured Veh.	XD 9748L	Veh. Inspected		GBC 2606A
	Policy No.	Z/21/VC00/112656	Coverage (\$)		0.00
	Claim No.	21/22/22/VC00/025780	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		11/05/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 1.5L	c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.	VSKYBAM20U0021681	Colour		WHITE
	Odometer	229046 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	175/70 R14	ROTALLA		6 mm
	L/H Front Tyre	175/70 R14	ROTALLA		6 mm
	R/H Rear Tyre	175/70 R14	ROTALLA		6 mm
	L/H Rear Tyre	175/70 R14	ROTALLA		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	09/05/2022	Inspect Date /	Time	12/05/2022 (12:00 PM)
	Survey held at	AUTO MEGA MALL PTE LTD			
		24 DEFU LANE 12 SINGAPORE 539131			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22004487/Gpa3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor