

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004489/AVY3Q2**Date:** 25/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00216562100

Claimant Vehicle No : SLZ3108A **Insured Vehicle No :** SKU1484P

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No: SNM22D203237/C03/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ3108A**

Make & Model: HONDA CIVIC, 1.6 (A) Engine No: R16B25500419

Reg. Date: 27/04/2018 (Man. Year: 2018) Chassis No: MRHFC5650JT000387

Colour: Black Odometer: 85102 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,123.28	7,328.32	9,794.96	57.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,490.00	3,280.00	5,210.00	61.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,613.28	10,608.32	15,004.96	58.58
Approved Total (Overridden) (S\$)		8,500.00		
Nett Amount (S\$)	25,613.28	8,500.00	17,113.28	66.81

INSPECTION

Date of Assignment: 18/08/2022

Date Inspected: 12/05/2022 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki
Bukit
Singapore 415875

Estimated Period of Repair: 11.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Aug 2022)
Parts:	143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ3108A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT FENDER LH	Dented	526.40 FL	*526.40 FL
2	2	*FRONT FENDER INNER SPONGE	Not Necessary	152.80 FL	*- FL
3	2	*FRONT FENDER COWLING	Deformed	264.20 FL	*155.00 FL
4	1	*FRONT WINDSCREEN MOULDING	Not Necessary	174.20 FL	*- FL
5	1	*FRONT LOWER ARM LH	Not Necessary	427.20 FL	*- FL
6	1	*FRONT KNUCKLE ARM LH	Not Necessary	434.50 FL	*- FL
7	1	*FRONT SHOCK ABSORBER LH	Not Necessary	329.60 FL	*- FL
8	1	*FRONT LINKAGE LH	Not Necessary	155.60 FL	*- FL
9	1	*FRONT WHEEL HUP WITH BEARING LH	Not Necessary	263.70 FL	*- FL
10	1	*FRONT DOOR PILLAR (OUTER) RH	Repair	879.40 FL	*- FL
11	1	*FRONT DOOR SIDE MIRROR RH	Cut	1,264.50 FL	*740.00 FL
12	1	*FRONT DOOR LH	Dented	1,694.80 FL	*895.00 FL
13	2	*FRONT DOOR STOPPER	Not Necessary	32.40 FL	*- FL
14	2	*FRONT DOOR HINGE LH	Not Necessary	105.40 FL	*- FL
15	1	*FRONT DOOR CHECK LH	Not Necessary	98.40 FL	*- FL
16	1	*FRONT DOOR SPEAKER LH	Not Necessary	196.30 FL	*- FL
17	1	*FRONT DOOR WIRE HARNESS LH	Not Necessary	471.40 FL	*- FL
18	1	*FRONT DOOR INNER TRIM LH	Not Necessary	498.10 FL	*- FL
19	1	*FRONT DOOR INNER LOCK LH	Damaged	299.10 FL	*299.10 FL
20	1	*FRONT DOOR LOCK CATCHER LH	Not Necessary	25.40 FL	*- FL
21	1	*FRONT DOOR WEATHERSTRIP LH	Not Necessary	137.20 FL	*- FL
22	1	*FRONT DOOR OUTER STRIP LH	Not Necessary	120.10 FL	*- FL
23	1	*FRONT DOOR LOWER INNER RUBBER LH	Not Necessary	59.60 FL	*- FL
24	1	*FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR LH	Not Necessary	399.40 FL	*- FL
25	1	*FRONT DOOR GLASS CHANNEL LH	Not Necessary	72.80 FL	*- FL
26	1	*FRONT DOOR FRAME WEATHER STRIP LH	Not Necessary	168.90 FL	*- FL
27	1	*ROCKER PANEL LH (OUTER)	Repair	363.70 FL	*- FL
28	1	*SET SIDE SKIRT	Cracked	439.50 FL	*439.50 FL
29	1	*REAR DOOR LH	Dented	798.90 FL	*798.90 FL
30	2	*REAR DOOR LOWER RUBBER LH	Not Necessary	111.40 FL	*- FL
31	1	*REAR DOOR HINGE LH	Not Necessary	52.70 FL	*- FL
32	1	*REAR DOOR INNER LOCK LH	Damaged	234.60 FL	*234.60 FL
33	1	*FRONT DOOR LOCK CATCHER LH	Not Necessary	25.40 FL	*- FL
34	1	*FRONT DOOR INNER TRIM LH	Cracked	469.80 FL	*469.80 FL
35	1	*REAR DOOR WEATHER STRIP LH	Not Necessary	118.60 FL	*- FL
36	1	*REAR DOOR POWER WINDOW MOTOR C/W REGULATOR LH	Damaged	341.70 FL	*341.70 FL
37	1	*REAR DOOR GLASS CHANNEL LH	Not Necessary	65.80 FL	*- FL
38	1	*REAR DOOR OUTER STRIP LH	Not Necessary	108.70 FL	*- FL
39	1	*REAR FENDER LH	Dented	798.20 FL	*798.20 FL
40	1	*REAR FENDER QUARTER GLASS MOULDING LH	Necessary	58.30 FL	*58.30 FL
41	1	*REAR FENDER COWLING LH	Not Necessary	172.20 FL	*- FL
42	1	*REAR WINDSCREEN MOULDING	Necessary	156.70 FL	*156.70 FL
43	1	*REAR LOWER ARM LH	Bent	198.30 FL	*198.30 FL
44	1	*REAR UPPER ARM LH	Bent	187.20 FL	*187.20 FL
45	1	*REAR SWING ARM LH	Bent	216.10 FL	*216.10 FL
46	1	*REAR SHOCK ABSORBER LH	Bent	321.50 FL	*321.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR LINKAGE LH	Not Necessary	98.70 FL	*- FL
48	1		*REAR WHEEL HUP C/W BEARING LH	Damaged	389.60 FL	*389.60 FL
49	1		*REAR KNUCKLE ARM LH	Damaged	347.80 FL	*347.80 FL
50	1		*REAR ABS SENSOR LH	Not Necessary	298.80 FL	*- FL
51	1		*REAR BUMPER	Deformed	617.20 FL	*617.20 FL
52	1		*REAR BUMPER SIDE REFLECTOR GARNISH LH	Not Necessary	120.30 FL	*- FL
53	1		*REAR BUMPER SIDE BRACKET	Not Necessary	122.30 FL	*- FL
54	1		*REAR BUMPER SIDE RETAINER	N/S Necessary	156.20 FL	*32.00 FL
55	1		*SET FRONT BUMPER CLIP	Not Necessary	80.00 FS	*- FS
56	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	50.00 FS	*30.00 FS
57	1		*FRONT WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
58	1		*FRONT WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
59	1		*FRONT DOOR PILLAR (OUTER) SEALANT RH	Not Necessary	120.00 FS	*- FS
60	1		*FRONT WHEEL RIM LH	Not Necessary	850.00 FS	*- FS
61	1		*SET SIDE SKIRT CLIP	Necessary	80.00 FS	*30.00 FS
62	1		*REAR FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
63	1		*SET REAR FENDER COWLING CLIP RH	Not Necessary	60.00 FS	*- FS
64	1		*REAR FENDER GLASS SEALANT RH	Necessary	80.00 FS	*40.00 FS
65	1		*REAR FENDER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS
66	1		*REAR WINDSCREEN SEALANT	Necessary	180.00 FS	*40.00 FS
67	1		*REAR WINDSCREEN INNER SEAL	Necessary	80.00 FS	*30.00 FS
68	1		*REAR WHEEL TYRE LH	Not Necessary	800.00 FS	*- FS
69	1		*REAR WHEEL RIM LH	Cut	850.00 FS	*550.00 FS
70	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
71	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
72	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	20,451.60	8,972.90
- List Item Discount on L Items 20.00/20.00% (\$)	3,328.32	1,644.58
Total Parts (\$)	17,123.28	7,328.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,500.00	1,200.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	1,300.00
3	WIRING CHECK	New	250.00	30.00
4	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	80.00
5	REMOVE AND REFIX FRONT DASHBOARD	New	1,200.00	0.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
7	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
8	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	0.00
9	TRANFER FRONT DOOR MECHANISM	New	80.00	80.00
10	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	220.00
11	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
12	FOUR WHEEL ALIGNMENT	New	120.00	80.00
13	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
14	TRANFER REAR DOOR MECHANISM	New	80.00	80.00
15	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
16	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
17	REMOVE AND REFIX REAR FENDER GLASS RH	New	80.00	40.00
18	RESET ABS LIGHT	New	350.00	0.00
19	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			8,490.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >