

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004491/AVY3M4**Date:** 21/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00216562100

Claimant Vehicle No : SKX5630S **Insured Vehicle No :** SKU1484P

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No: SNM22D203237/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX5630S**

Make & Model: TOYOTA COROLLA ALTIS, 1.6 Classic (A) Engine No: 1ZRX534959

Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No: MR053REH104540349

Colour: White Odometer: 80393 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,457.44	6,590.72	14,866.72	69.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,070.00	1,840.00	3,230.00	63.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,527.44	8,430.72	18,096.72	68.22
Approved Total (Overridden) (S\$)		6,700.00		
Nett Amount (S\$)	26,527.44	6,700.00	19,827.44	74.74

INSPECTION

Date of Assignment: 12/05/2022

Date Inspected: 12/05/2022 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jul 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 Classic (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX5630S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	539.30 FL	*539.30 FL
2	1		*FRONT BUMPER FOG LAMP RH	Cracked	310.90 FL	*310.90 FL
3	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	123.10 FL	*123.10 FL
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	170.80 FL	*- FL
5	1		*FRONT GRILLE TOP RUBBER	Not Necessary	145.60 FL	*- FL
6	1		*FRONT BUMPER BOTTOM COVER	Not Necessary	156.50 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER (2PCS)	O/s Damaged	170.20 FL	*85.10 FL
8	1		*FRONT BUMPER REINFORCEMENT SPONGE	Cracked	102.20 FL	*102.20 FL
9	1		*FRONT BUMPER REINFORCEMENT	Dented	397.30 FL	*397.30 FL
10	1		*FRONT GRILLE LOGO	Necessary	48.90 FL	*48.90 FL
11	1		*FRONT RADIATOR GRILLE C/W CHROME	Cracked	643.80 FL	*466.00 FL
12	1		*FRONT FENDER RH	Buckled	781.20 FL	*781.20 FL
13	1		*FRONT FENDER EMBLEM (VVTI) RH	Necessary	38.90 FL	*38.90 FL
14	1		*FRONT FENDER INNER COWLING (2PCS)	O/s Torn	398.40 FL	*199.20 FL
15	1		*FRONT FENDER SUPPORT BRACKET RH	Repair	85.30 FL	*- FL
16	1		*FRONT WHEEL HOUSE EXTEND PANEL RH	Repair	295.50 FL	*- FL
17	1		*FRONT ABS SENSOR RH	Not Necessary	543.91 FL	*- FL
18	1		*FRONT CROSS MEMBER	Not Necessary	2,024.10 FL	*- FL
19	1		*FRONT KNUCKLE ARM RH	Not Necessary	628.10 FL	*- FL
20	1		*FRONT LOWER ARM RH	Bent	732.50 FL	*602.00 FL
21	1		*FRONT KNUCKLE ARM BEARING RH	Damaged	128.10 FL	*128.10 FL
22	1		*FRONT STABILIZER BAR LINKAGE RH	Not Necessary	237.20 FL	*- FL
23	1		*FRONT DRIVESHAFT RH	Not Necessary	1,287.50 FL	*- FL
24	1		*FRONT SHOCK ABSORBER RH	Not Necessary	438.80 FL	*- FL
25	1		*FRONT STEERING RACK AND PINION	Not Necessary	1,955.70 FL	*- FL
26	1		*HEADLAMP (2PCS)	O/s Cracked	5,999.12 FL	*2,816.00 FL
27	4		*HEAD LAMP LOWER BRACKET	Not Necessary	248.40 FL	*- FL
28	1		*BONNET	Not Necessary	1,248.60 FL	*- FL
29	2		*BONNET HINGE	Not Necessary	150.20 FL	*- FL
30	2		*BONNET STOPPER	Not Necessary	49.60 FL	*- FL
31	1		*BONNET LOCK	Not Necessary	135.70 FL	*- FL
32	1		*BONNET LOCK BRACE PANEL	Not Necessary	149.60 FL	*- FL
33	1		*FRONT SUPPORT PANEL	Buckled	1,136.70 FL	*997.00 FL
34	1		*WASHER TANK	Deformed	219.10 FL	*219.10 FL
35	1		*WASHER TANK MOTOR	Not Necessary	245.60 FL	*- FL
36	1		*AIR CONDENSOR	Not Necessary	1,801.70 FL	*- FL
37	1		*RADIATOR	Not Necessary	239.70 FL	*- FL
38	2		*RADIATOR TOP BRACKET	Not Necessary	119.40 FL	*- FL
39	4		*RADIATOR MOUNTING	Not Necessary	98.00 FL	*- FL
40	1		*RADIATOR TOP GARNISH	Not Necessary	128.70 FL	*- FL
41	1		*RADIATOR SPARE TANK	Not Necessary	125.30 FL	*- FL
42	1		*FRONT NUMBER PLATE	Not Necessary	80.00 FS	*- FS
43	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
44	1		*SET FRONT BUMPER BOTTOM COVER GARNISH CLIP	Not Necessary	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET FRONT RADIATOR GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
46	1		*SET FRONT FENDER COWLING CLIPS	Necessary	80.00 FS	*30.00 FS
47	1		*SET FRONT FENDER UPPER CORNER GARNISH CLIP LH	Not Necessary	50.00 FS	*- FS
48	1		*BONNET SEALANT	Not Necessary	150.00 FS	*- FS
49	1		*SET BONNET INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
50	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
51	1		*SET RADIATOR TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
52	1		*FRONT WHEEL TYRE LH	Not Necessary	580.00 FS	*- FS
53	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
54	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS
55	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
56	1		*FRONT WHEEL RIM RH	Cut	1,508.02 FS	*580.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,577.25	8,554.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	6,119.81	1,963.58
Total Parts (\$\$)	21,457.44	6,590.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	1,400.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	700.00
3	WIRING CHECK	New	80.00	30.00
4	TUFF COAT	New	250.00	60.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	350.00	0.00
6	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
7	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
8	REFOCUS HEADLAMP BEAM	New	60.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	150.00
10	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
11	FOUR WHEEL ALIGNMENT	New	120.00	80.00
12	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	300.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			5,070.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >