



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22004493/Rny3m4	
			Date: 05/08/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SBS 3441S	Veh. Inspected	GBD 7593P	
Policy No.	D-19094111MFB	Coverage (\$)	0.00	
Claim No.	D22001342MFBP	Excess (\$)	0.00	
Assign From	HARMINDER KAUR	Assign Date	12/05/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	VOLKSWAGEN CADDY 1.6 TDI MT	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WV1ZZZ2KZFX108976	Colour	WHITE	
Odometer	198141 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/04/2022	Inspection Date	19/05/2022	
Survey held at	38 WOODLANDS RD #01-14, WOODLANDS IND PARK E1			
Repairer	TWIN WHEELS AUTO TRADING ENTERPRISE			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	