



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGG 9711C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LEFT LINING, FRONT FLOOR (SN)	STAINED BY WATER	998.37	998.37
1	RIGHT LINING, FRONT FLOOR (SN)	STAINED BY WATER	1,092.74	1,092.74
1	LINING, REAR FLOOR (SN)	STAINED BY WATER	1,484.53	1,484.53
1	MAIN ELECTRICAL WIRING HARNESS (SN)	STAINED BY WATER	10,173.93	10,173.93
1	INSTRUMENT CLUSTER (SN)	NOT NECESSARY	3,633.08	-
1	SPARK-IGNITION ENGINE (SN)	NOT NECESSARY	34,763.76	-
1	RH/LOWER A-PILLAR FUSE BOX (SN)	NOT NECESSARY	218.01	-
1	IGNITION / STARTER SWITCH CONTROL UNIT (SN)	STAINED BY WATER	689.25	689.25
1	FUEL PUMP CONTROL UNIT, COMPLETE (SN)	NOT NECESSARY	444.79	-
1	ELECTRICAL SYSTEM BATTERY (SN)	NOT NECESSARY	911.49	-
1	BATTERY CURRENT LIMITER (SN)	NOT NECESSARY	368.45	-
1	SRS CONTROL UNIT, COMPLETE (SN)	NOT NECESSARY	1,126.73	-
1	LEFT SEAT HEIGHT ADJUSTMENT (SN)	NOT NECESSARY	3,704.59	-
1	RIGHT SEAT HEIGHT ADJUSTMENT (SN)	NOT NECESSARY	3,704.59	-
1	COCKPIT ELECTRICAL WIRING HARNESS (SN)	STAINED BY WATER	3,230.46	3,230.46
1	RH/FRONT SEAT BELT (SN)	STAINED BY WATER	731.35	731.35
1	LH/FRONT SEAT BELT (SN)	STAINED BY WATER	731.35	731.35
1	BODY-SIDE ENGINE WIRING HARNESS (SN)	STAINED BY WATER	3,318.86	3,318.86
1	COVER (SN)	BROKEN	24.60	24.60
1	CLAMP (SN)	NECESSARY	22.35	22.35
1	RADIATOR ANTIFREEZE (SN)	NECESSARY	34.86	34.86
			71,408.14	22,532.65



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	FRAME FLOOR WIRING HARNESS REPLACE WITH REMOVE / INSTALL EVAPORATOR UNIT INSTRUMENT PANEL & HEADLINER & STEERING COLUMN & AIRBAG & FUSE BOX DETACHABLE PARTS IN AREA TO BE REPAIRED.		14,400.00	12,480.00
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,440.00	960.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	REMOVE, REPLACE RADIATOR, CONDENSER COOLING SYSTEM & FITTINGS VACUUM AND REGAS.		500.00	500.00
	REMOVE / INSTALL ENGINE WITH AUTOMATIC TRANSMISSION.	NOT NECESSARY	2,160.00	-
	CHECK & RECTIFY ALL ELECTRONICS PARTS & WIRING TO IDENTIFICATION.		2,160.00	1,920.00
	TRANSFER ALL ATTACHED COMPONENT TO NEW ENGINE.	NOT NECESSARY	1,920.00	-
	SEAT AND FLOOR COVERING (ALL) REMOVE / INSTALL, TO REPLACE FLOOR COVERING.		2,400.00	1,920.00
	CLEAN VEHICLE INTERIOR FLOOR.		960.00	960.00
	TO REMOVE / REPLACE EXHAUST SYSTEM.	NOT NECESSARY	420.00	-
			26,740.00	19,120.00
<b>GRAND TOTAL</b>			<b>98,148.14</b>	<b>41,652.65</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>41,652.65</b>

Report Ref No. CS/AIS22004495/Eqy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.