

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004496/KQY3Q2**Date:** 13/10/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00156242100
Claimant Vehicle No :	SNC8405G	Insured Vehicle No :	GBB7280C
Date of Loss:	12/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203264/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNC8405G	Engine No:	HIDDEN
Make & Model:	TESLA MODEL 3 STANDARD RANGE, (A)	Chassis No:	LRW3F7FA8MC385216
Reg. Date:	19/11/2021 (Man. Year: 2021)	Odometer:	6269 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45Z R18	Rear Tyre Size:	235/45Z R18
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,484.35	5,802.21	682.14	10.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,120.00	1,880.00	1,240.00	39.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	9,604.35	7,682.21	1,922.14	20.01
+ GST 7.00/7.00% (\$\$)	672.30	537.75	134.55	20.01
Nett Amount (\$\$)	10,276.65	8,219.96	2,056.69	20.01

INSPECTION

Date of Assignment:	12/05/2022	
Date Inspected:	13/05/2022 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$7,682.20

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Oct 2022)

Parts: 143 TESLA MODEL 3 STANDARD RANGE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNC8405G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	728.97 FL	*728.97 FL
2	1		*REAR BOOTLID TESLA EMBLEM	Necessary	37.38 FL	*37.38 FL
3	1		*REAR BOOTLID LAMP LH	Broken	177.57 FL	*177.57 FL
4	1		*REAR BOOTLID LAMP RH	Mtg Cracked	177.57 FL	*177.57 FL
5	1		*REAR BOOTLID NUMBER PLATE LAMP LH	Serviceable	14.95 FL	*- FL
6	1		*REAR BOOTLID NUMBER PLATE LAMP RH	Serviceable	14.95 FL	*- FL
7	1		*REAR BOOTLID OUTER HANDLE WITH REVERSE CAMERA	Dented	121.50 FL	*121.50 FL
8	1		*REAR BOOTLID MECHANISM LOCK	Repair	54.21 FL	*- FL
9	1		*REAR BOOTLID LOCK STRIKER	Repair	52.34 FL	*- FL
10	1		*REAR BOOTLID INNER TRIM BOARD	Mtg Cracked	345.79 FL	*345.79 FL
11	1		*REAR BOOTLID HINGE LH	Distorted	61.68 FL	*61.68 FL
12	1		*REAR BOOTLID HINGE RH	Distorted	61.68 FL	*61.68 FL
13	1		*REAR BOOTLID WEATHERSTRIP	Distorted	121.50 FL	*121.50 FL
14	1		*REAR TAIL LAMP LH	Cracked	280.37 FL	*280.37 FL
15	1		*REAR TAIL LAMP RH	Mtg Cracked	280.37 FL	*280.37 FL
16	1		*REAR TAIL LAMP BRACKET LH	Serviceable	2.80 FL	*- FL
17	1		*REAR TAIL LAMP BRACKET RH	Serviceable	2.80 FL	*- FL
18	1		*REAR BUMPER	Bent	663.55 FL	*663.55 FL
19	1		*REAR BUMPER SIDE BRACKET LH	Serviceable	7.48 FL	*- FL
20	1		*REAR BUMPER SIDE BRACKET RH	Cracked	7.48 FL	*7.48 FL
21	1		*REAR BUMPER CENTER BRACKET	Cracked	52.34 FL	*52.34 FL
22	1		*REAR BUMPER LOWER LIP	Dented	140.19 FL	*140.19 FL
23	1		*REAR BUMPER UNDER COVER	Cracked	205.61 FL	*205.61 FL
24	1		*REAR BUMPER REFLECTOR LH	Broken	20.56 FL	*20.56 FL
25	1		*REAR BUMPER REFLECTOR RH	Serviceable	20.56 FL	*- FL
26	4		*REAR BUMPER PARKING SENSOR	Shorted (1 PCS ONLY)	635.62 FL	*158.88 FL
27	4		*REAR BUMPER PARKING SENSOR BRACKET	Necessary	18.68 FL	*18.68 FL
28	1		*REAR BUMPER REINFORCEMENT	Bent	271.03 FL	*271.03 FL
29	1		*REAR END PANEL	Bent	448.60 FL	*448.60 FL
30	1		*REAR END PANEL TOP GARNISH	Dented	299.07 FL	*299.07 FL
31	1		*REAR BOOTLID INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
32	1		*REAR BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
33	1		*REAR END PANEL JOINT SEALANT	Necessary	80.00 FS	*30.00 FS
34	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
35	1		*FRONT SAFETY SEAT BELT LH	Jammed	158.88 FL	*158.88 FL
36	1		*FRONT SAFETY SEAT BELT RH	Jammed	158.88 FL	*158.88 FL
37	1		*REAR SAFETY SEAT BELT LH	Jammed	149.53 FL	*149.53 FL
38	1		*REAR SAFETY SEAT BELT RH	Jammed	149.53 FL	*149.53 FL
39	1		*REAR SAFETY SEAT BELT CENTRE	Jammed	135.51 FL	*135.51 FL
40	1		*BATTERY PYRO DISCONNECTOR ASSY	Necessary	22.18 FL	*22.18 FL
41	1		*RESTRAINT CONTROL MODULE	Necessary	560.75 FL	*560.75 FL
42	1		*REAR BLE ASSEMBLY	Missing	29.91 FL	*29.91 FL
43	1		*REAR SPARE TYRE PANEL TOP CARD BOARD	Cracked	186.92 FL	*186.92 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR TRUNK LUGGAGE COMPARTMENT	Cracked	58.88 FL	*58.88 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	7,178.17 6,431.34
					- List Item Discount on L Items 10.00/10.00% (S\$)	693.82 629.13
					Total Parts (S\$)	6,484.35 5,802.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS & ETC	New	1,000.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC	New	1,000.00	660.00
3	TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS & ETC	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR	New	150.00	60.00
5	TO DAIGNOSIS FAULT CODE & RESET MEMORY	New	150.00	150.00
6	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	20.00
7	TO TUFF KOTE & UNDERSEAL MATERIALS	New	180.00	30.00
8	CERAMIC COATING	New	400.00	300.00
Gross Labour Cost (\$\$)			3,120.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >