



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDL 1528C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	676.90	589.40
1	REAR BUMPER SENSOR	SCRATCHED	350.00	285.00
1	REAR BUMPER REFLECTOR LEFT	CUT	69.60	69.60
2	REAR BUMPER RETAINER	O/S DISTORTED	221.80	110.90
1	REAR PANEL	TO REPAIR SEE LABOUR	675.60	-
1	EXHAUST BOX	TO REPAIR SEE LABOUR	1,089.80	-
1	TAIL LAMP	CUT	489.60	489.60
	LESS 25% DISCOUNT		-	-386.13
			3,573.30	1,158.37
	<u>LABOUR</u>			
	RUST PROOFING.	NOT NECESSARY	80.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR PANEL AND EXHAUST BOX.		650.00	200.00
	SPRAY PAINTING		600.00	220.00
			1,330.00	420.00
	GRAND TOTAL		4,903.30	1,578.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CS/SMO22004499/Kvy3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.