



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 2080Z

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|----------------------------------|--------------------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | BALANCER (L.H.) | NOT NECESSARY | 55.00 | - |
| 1 | BALANCER (R.H.) | CUT | 55.00 | 55.00 |
| 2 | BIKE EMBLEM "DOWNTOWN" @ \$35.00 | NECESSARY | 70.00 | 70.00 |
| 1 | COOLANT 2L | NOT NECESSARY | 75.00 | - |
| 1 | EXHAUST ENDCAN | TO REPAIR SEE LABOUR | 850.00 | - |
| 1 | EXHAUST PROTECTOR | CUT | 150.00 | 150.00 |
| 1 | EXHAUST REAR PROTECTOR | CUT | 85.00 | 85.00 |
| 1 | FAIRING COVERSET | CUT / CRACKED | 2,600.00 | 1,650.00 |
| 1 | FOOR REST COVER (L.H.) (CUT) | NOT CONSISTENT WITH THE IMPACT | 145.00 | - |
| 1 | FOOR REST COVER (R.H.) | CUT | 145.00 | 145.00 |
| 1 | FRONT BRAKE CALIPER | NOT NECESSARY | 450.00 | - |
| 1 | FRONT BRAKE DISC | NOT NECESSARY | 350.00 | - |
| 1 | FRONT BRAKE LEVER | CUT | 65.00 | 65.00 |
| 1 | FRONT BRAKE RESERVOIR | NOT NECESSARY | 350.00 | - |
| 1 | FRONT COMPLETE FORK KIT | BENT / TWISTED | 1,650.00 | 850.00 |
| 1 | FRONT CUP HOLDER | NOT NECESSARY | 25.00 | - |
| 1 | FRONT DASHBOARD COVER | CUT | 280.00 | 280.00 |
| 1 | FRONT FORK BRACE | BENT | 235.00 | 235.00 |
| 1 | FRONT HEADLIGHT | NOT NECESSARY | 650.00 | - |
| 1 | FRONT LEFT COOLANT CONTAINER | NOT NECESSARY | 95.00 | - |
| 1 | FRONT MIRROR (L.H.) | NOT NECESSARY | 45.00 | - |
| 1 | FRONT MIRROR (R.H.) | CUT | 45.00 | 45.00 |
| 1 | FRONT NUMBER PLATE | NOT NECESSARY | 35.00 | - |
| 1 | HANDLEBAR | BENT | 165.00 | 165.00 |
| 1 | RACK | NOT NECESSARY | 65.00 | - |
| 1 | RADIATOR | CUT | 485.00 | 485.00 |
| 1 | REAR AIR FILTER BOX COVER (CUT) | NOT CONSISTENT WITH THE IMPACT | 65.00 | - |
| 1 | REAR BRAKE RESERVOIR | NOT NECESSARY | 350.00 | - |

Report Ref No. CS/SMO22004500/Uvy3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--------------------------------|---------------------------|-------------------|
| 1 | REAR CVT COVER (CUT) | NOT CONSISTENT WITH THE IMPACT | 230.00 | - |
| 1 | REAR NUMBER PLATE | NOT NECESSARY | 35.00 | - |
| 1 | REAR RACK HOLDER | NOT NECESSARY | 295.00 | - |
| 1 | REAR TOP CASE | NOT NECESSARY | 85.00 | - |
| 1 | SEAT COVER (DAMAGED) | NOT CONSISTENT WITH THE IMPACT | 95.00 | - |
| 1 | SIDE STAND | NOT NECESSARY | 95.00 | - |
| 1 | WINDSHIELD | NOT NECESSARY | 285.00 | - |
| | LESS 10% DISCOUNT | | - | -428.00 |
| | | | 10,755.00 | 3,852.00 |
| | LABOUR | | | |
| | FRAME ALIGNMENT & LABOUR CHARGE. INCLUSIVE OF THE REPAIR OF EXHAUST ENDCAN. | | 350.00 | 300.00 |
| | SPRAY PAINTING. | | 400.00 | 300.00 |
| | | | 750.00 | 600.00 |
| | GRAND TOTAL | | 11,505.00 | 4,452.00 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,500.00 |

Report Ref No. CS/SMO22004500/Uvy3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.