



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 28D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (WCP)	TO REPAIR SEE LABOUR	840.00	-
1	REAR BUMPER REFLECTOR RH (WCP)	CUT	230.00	230.00
1	REAR BUMPER PARKING SENSOR OUTER RH (WCP)	NOT NECESSARY	170.00	-
	COST PLUS 10%		124.00	23.00
			1,364.00	253.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SUNDRIES (SN)	NOT NECESSARY	20.00	-
			70.00	30.00
	<b><u>LABOUR</u></b>			
	REMOVE, REFIT AND REPAIR AFFECTED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER.		400.00	250.00
	TO REMOVE & REFIT REAR BUMPER PARKING SENSORS.		50.00	30.00
	SIMPLE WIRING.		20.00	20.00
	ANTI RUST COATING.	NOT NECESSARY	20.00	-
	PAINT MATERIALS PER PANEL.		400.00	250.00
			890.00	550.00
	<b>GRAND TOTAL</b>		<b>2,324.00</b>	<b>833.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>833.00</b>
------------------------------------	--	--	---------------

Report Ref No. CS6/AIS22004501/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.