

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBS 3426L**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	L/H FRONT SIGNAL LAMP	BROKEN	85.00	85.00
1	L/H SIDE MIRROR	GRAZED	60.00	60.00
1	CLUTCH LEVER	GRAZED	48.00	48.00
1	L/H BALANCER	DAMAGED	45.00	35.00
1	L/H FRONT COVER	GRAZED	130.00	130.00
1	L/H FLOORBOARD	DISTORTED	110.00	110.00
1	L/H FRONT TOP COVER	BROKEN	150.00	64.20
1	AIR FILTER COVER	SCRATCHED	85.00	85.00
1	MAINSTAND	BENT	95.00	95.00
1	GEARBOX COVER	CRACKED	240.00	240.00
1	HANDLEBAR	SERVICEABLE	350.00	-
	LESS 10% DISCOUNT		-	-95.22
			1,398.00	856.98
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BOX (SN)	GRAZED	450.00	300.00
			450.00	300.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE AND REPAIR DAMAGED PARTS.		600.00	250.00
	TO CHECK WIRING AND REWIRE.	NOT NECESSARY	60.00	-
	TO STRAIGHTEN AND ALIGN STRUCTURAL BODY FRAME.	NOT NECESSARY	480.00	-
	TO SPRAY-PAINT OF AFFECTED AREAS.	NOT NECESSARY	200.00	-
			1,340.00	250.00
<b>GRAND TOTAL</b>			<b>3,188.00</b>	<b>1,406.98</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,100.00</b>

Report Ref No. CS3/ASM21004821/Gqy3e2-1

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.