

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29679 Date: 06<sup>th</sup> Jun 2022

Our Ref: CS3/ASM21004821/Gqy3e2-1

## M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## **EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBS 3426L**

INSURED VEHICLE: YP 5702U ACCIDENT DATE: 14/04/2021

We thank you for your instruction on 12/05/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBS 3426L from M/s Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement and Police Report of Vehicles FBS 3426L and YP 5702U.
- c) Colour damaged vehicle photographs of SMD 9888X.

Pre-Repair Inspection Date: 16/04/2021 at M/s Candymotor Workshop Pte Ltd, 25 Kaki Bukit Road 4 #01-83 Synergy @ KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBS 3426L

Make & Model : Honda ADV150 ABS CVT

Year of Registration : 2021

Chassis Number : MH1KF6119MK032872

Engine Capacity : 149 cc

- 2. We recommend that the repairs of the entire damage require about <u>3 (Three)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.