

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22004503/GNCE2**Date:** 18/11/2022REFERENCE

Insured/Claimant:	FOO ANQI SHARON	Policy No:	7210049960-01	
Date of Loss:	07/05/2022	Nature of Claim:	OD	Claim No: 5677580993SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMZ9693A		
Make & Model:	AUDI A3, 1.5 SEDAN TFSI S TRONIC (18") (A)	Engine No:	DFY272235
Reg. Date:	27/05/2021 (Man. Year: 2021)	Chassis No:	WAUZZZGY3MA100989
Colour:	Grey	Odometer:	7549 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	S\$158,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,906.00	2,295.60	2,610.40	53.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,922.00	2,942.00	2,980.00	50.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,828.00	5,237.60	5,590.40	51.63
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	10,028.00	4,437.60	5,590.40	55.75
+ GST 7.00/7.00% (S\$)	701.96	310.63	391.33	55.75
Nett Amount (S\$)	10,729.96	4,748.23	5,981.73	55.75

INSPECTION

Date of Assignment:	13/05/2022	
Date Inspected:	12/05/2022	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-LH	Buckled	2,466.00 FS	*1,972.80 FS
2	1		*REAR DOOR OUTER SEAL-LH	Necessary	179.00 FS	*142.80 FS
3	1		*REAR DOOR CATCH	Not Necessary	0.00 FS	*- FS
			NPA			
4	1		*REAR WHEEL SPOILER-LH	Not Necessary	32.00 FS	*- FS
5	1		*REAR WHEEL HOUSING LINER-LH	Not Necessary	260.00 FS	*- FS
6	1		*REAR ALUMINIUM RIM	Not Necessary	1,435.00 FS	*- FS
7	1		*RUBBER VALVE	Not Necessary	4.00 FS	*- FS
8	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
9	1		*SUNDRIES	Not Necessary	350.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					4,906.00	2,295.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	350.00	350.00
2	TO DISMANTLE AND RENEW LHS REAR DOOR.TO REPAIR LHS SILL PANEL AND LHS REAR FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	750.00
3	TO RESPRAY LHS REAR DOOR,LHS SILL PANEL AND LHS REAR FENDER	New	3,000.00	1,650.00
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,922.00	2,942.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >