

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5735A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, RR BUMPER ASSY (DISC 25%)	CRACKED	485.60	364.20
2	PAD, RR BUMPER, RH & LH, 3 @\$11.00 (DISC 25%)	NECESSARY	22.00	16.50
2	PAD, RR BUMPER, RH & LH, 2 @\$4.00 (DISC 25%)	NECESSARY	8.00	6.00
2	PAD, RR BUMPER, RH & LH, 1 @\$4.00 (DISC 25%)	NECESSARY	8.00	6.00
2	SEAL, RR BUMPER ARM, RH & LH @\$11.30 (DISC 25%)	NECESSARY	22.60	16.95
1	RETAINER, RR BUMPER, RH (DISC 25%)	DISTORTED	132.60	99.45
10	CLIPS PIECE, FRT & RR BUMPER @\$4.50 (DISC 25%)	NECESSARY	45.00	33.75
1	GUARD, RR BUMPER, LOWER (DISC 25%)	DENTED	374.50	280.88
3	PAD, RR BUMPER, CTR @\$11.00 (DISC 25%)	NECESSARY	33.00	24.75
1	COVER, REAR COMBINATION LAMP, RH (DISC 25%)	DENTED	69.90	52.43
1	LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%)	CRACKED	339.60	305.64
1	LENS & BODY, REAR COMBINATION LAMP, NO.2 RH (DISC 10%)	CRACKED	261.00	234.90
1	LAMP ASSY, REAR, RH (DISC 10%)	CRACKED	293.60	264.24
1	SEAL, RR BUMPER, RH	SERVICEABLE	118.30	-
1	COVER, GUARD RR BUMPER LOWER	SERVICEABLE	22.00	-
1	REAR BUMPER REFLECTOR ASSY, REFLEX, RH	SERVICEABLE	39.00	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	SERVICEABLE	913.60	-
1	TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	SERVICEABLE	761.40	-
1	SPOILER SUB-ASSY, REAR	SERVICEABLE	1,575.40	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	ANTENNA, ELECTRICAL KEY	SERVICEABLE	72.00	-
1	COVER, REAR FLOOR UNDER, RH	SERVICEABLE	175.10	-
1	COVER, REAR FLOOR UNDER, LH	SERVICEABLE	241.90	-
1	COVER, REAR FLOOR UNDER CENTER	SERVICEABLE	229.90	-
1	LINER, REAR FENDER, RH	SERVICEABLE	139.80	-
1	TYRE	SERVICEABLE	126.74	-
2	TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE @\$28.90	NOT NECESSARY	57.80	-
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	NOT NECESSARY	30.90	-
1	TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	NOT NECESSARY	30.90	-

Report Ref No. CS/SMO22004512/Kqce2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	STRIDES LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 65558888	NOT NECESSARY	21.60	-
1	WHEEL, DISC	NOT NECESSARY	1,879.40	-
2	HUB & BEARING ASSY, RH & LH	NOT NECESSARY	668.90	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	332.70	-
2	TAIL GATE BACK DOOR HINGE ASSY, RH & LH @\$61.00	TO REPAIR SEE LABOUR	122.00	-
1	TAIL GATE PANEL SUB-ASSY, BACK DOOR	TO REPAIR SEE LABOUR	1,147.80	-
1	END PANEL SUB-ASSY, BODY LOWER BACK	TO REPAIR SEE LABOUR	651.00	-
1	PANEL SUB-ASSY, FENDER REAR RH	TO REPAIR SEE LABOUR	871.50	-
2	PATCH, SIDE PANEL REAR END, RH & LH	TO REPAIR SEE LABOUR	33.70	-
			12,546.54	1,705.69
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, TAIL GATE BACK DOOR HINGE ASSY, RH & LH, TAIL GATE PANEL SUB-ASSY, BACK DOOR, END PANEL SUB-ASSY, BODY LOWER BACK, PANEL SUB-ASSY, FENDER REAR RH AND PATCH, SIDE PANEL REAR END, RH & LH.		845.00	200.00
	SPRAY PAINT.		2,034.00	300.00
	TO REMOVE AND REFIX TAILGATE GLASS.	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	50.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,479.00	570.00
	GRAND TOTAL		16,025.54	2,275.69



Page No.:3 of 3

RECOMMENDED COST OF REPAIRS			2,275.69
-----------------------------	--	--	----------

Report Ref No. CS/SMO22004512/Kqce2

KONG SENG CHEONG

Licensed Appraiser