

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2304901

3 ANSON ROAD #16-00 SPRINGLEAF TOWER

SINGAPORE 079909

INV Date 01/08/2023

Reference CC6/CTI22004514/Kya3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMU 1214D

Insured Veh. SKU 7885B

Claim No. SNM22D203176/C02

Policy No. DMPCSNW00223672101

Accident Date 07/05/2022

Inspection Date 12/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	NSURANCE (S) PTE LTD		Ref:	CC6/CTI22004514/Kya3q2			
	3 ANSON ROAD # SPRINGLEAF TO\	16-00 WERSINGAPORE 079909		Date:	01/08/2023			
				Code:	CTI			
1.		Policy Particulars	:- THIRD PART	Y CLAIN	1			
	Insured Veh.	SKU 7885B	Veh. Inspected	t	SMU 1214D			
	Policy No.	DMPCSNW00223672101	Coverage (\$)		0.00			
	Claim No.	SNM22D203176/C02	Excess (\$)		0.00			
	Assign From		Assign Date		12/05/2022			
2.		Vehicle Partic	culars & Condit	ion				
	Make & Model	VOLKSWAGEN TOURAN (A)	c.c		1395			
	Engine No.	HIDDEN	Year of Reg.		2020			
	Chassis No.	WVGZZZ1TZKW072686	Colour		DARK BLUE			
	Odometer	28102 KM	Steering		IN ORDER			
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM			
	General	GOOD						
3.		Conditi	ons of Tyres					
		Size	Make		Balance			
	R/H Front Tyre	215/55 R17	PIRELLI		3 mm			
	L/H Front Tyre	215/55 R17	PIRELLI		3 mm			
	R/H Rear Tyre	215/55 R17	PIRELLI		6 mm			
	L/H Rear Tyre	215/55 R17	PIRELLI		6 mm			
4.		Description	on of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	BODY.					
	DAMAGES SEE D	ETAILS.						
5.		Genera	I Information					
	Accident Date	07/05/2022	Inspection Dat	te	12/05/2022			
	Survey held at	ALAN'S UNITED AUTO PTE LT)					
		BLK 7 SIN MING INDUSTRIAL E #01-76 SINGAPORE 575642	ESTATE					
5a.		Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b.	Estimate Days of Repair							
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days						
	•							



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMU 1214D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	450.00	-
1	FRONT N/S DOOR	BENT / WARPED	1,050.00	1,050.00
1	FRONT N/S DOOR RUBBER	NECESSARY	220.00	220.00
2	FRONT N/S DOOR HINGE @\$120.00	TO REPAIR SEE LABOUR	240.00	-
1	REAR N/S DOOR	BENT	1,050.00	1,050.00
1	REAR N/S DOOR RUBBER	NECESSARY	250.00	250.00
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	1,550.00	-
1	RR N/S FENDER GLASS C/W MOULDG	NOT NECESSARY	250.00	-
1	REAR N/S TAILLAMP	SERVICEABLE	350.00	-
1	REAR N/S BUMPER SIDE RETAINER	SERVICEABLE	90.00	-
1	N/S SPORT RIM	DENTED	1,120.00	1,120.00
	LESS 10% DISCOUNT		-662.00	-369.00
			5,958.00	3,321.00
	SPECIAL NETT ITEMS			
1	REAR N/S FENDER GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO CHECK AND ADJUST WHEEL ALIGNMENT.		65.00	60.00
	TO REMOVE AND ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO APPLY UNDERSEALING.		60.00	60.00
	TO REMOVE ROOF LINING, FRONT AND REAR SEATS, TRIM BOARD AND CARPET.		120.00	60.00
	TO PUTTY AND SPRAY REPLACED PARTS.		1,200.00	1,000.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF FRONT N/S FENDER, FRONT N/S DOOR HINGE AND REAR N/S FENDER.		1,000.00	700.00
			2,565.00	1,880.00
	GRAND TOTAL		8,583.00	5,201.00

Report Ref No. CC6/CTI22004514/Kya3q2





RECOMMENDED COST OF LUMP SUM REPAIRS		4,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI22004514/Kya3q2

KONG SENG CHEONG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 1214D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMU 1214D

RE-INSPECTION





