



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 3675R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BOOT LID	DENTED	1,035.60	1,035.60
1	BOOT LID LOGO	NOT NECESSARY	40.70	-
1	BOOT LID 'FIT' EMBLEM	NECESSARY	30.80	30.80
1	BOOT LID LOCK	DAMAGED	193.80	193.80
1	BOOT LID LOCK CHECKER	NOT NECESSARY	58.40	-
1	BOOT LID RUBBER	CUT	177.40	177.40
1	REAR WINDSCREEN RUBBER	NECESSARY	97.70	97.70
1	REAR PANEL	DENTED	495.10	495.10
1	REAR PANEL TRIM	DEFORMED	91.50	91.50
1	REAR BUMPER	DEFORMED	788.30	788.30
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	57.40	-
1	REAR BUMPER REFLECTOR -RH	NOT NECESSARY	99.30	-
1	TOOLS TRAY SPONGE	CRACKED	285.40	285.40
1	REAR BUMPER IMPACT BRACKET RH (ADDITIONAL)	DENTED	68.10	68.10
1	REAR END PANEL ANTENNA SENSOR (ADDITIONAL)	DAMAGED	178.20	178.20
1	REAR END PANEL BUZZER (ADDITIONAL)	DAMAGED	102.40	102.40
	LESS 20% DISCOUNT		-760.02	-708.86
			3,040.08	2,835.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEAL (SN)	NECESSARY	60.00	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	30.00
1	SET REAR PANEL TRIM CLIPS (SN)	NECESSARY	40.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	SET REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
			550.00	310.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN .		120.00	120.00
	TO REMOVE AND REFIT THIRD BRAKE LIGHT .	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT REAR VIDEO CAMERA.		80.00	50.00

Report Ref No. CS/SMO22004516/Aqcq2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REVERSE SENSOR .		80.00	50.00
	TO REMOVE AND REFIT REVERSE CAMERA.		80.00	50.00
	TO SPRAY PANEL SEALANT .		100.00	60.00
	TO REMOVE AND REFIT INNER TRIM .		100.00	60.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING WELDING WORKS.		1,000.00	850.00
	(REAR) TO SPRAY PAINTING.		1,000.00	800.00
			2,690.00	2,070.00
<b>GRAND TOTAL</b>			<b>6,280.08</b>	<b>5,215.44</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,150.00</b>
-----------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/SMO22004516/Aqcq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.