



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SND 1863H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BOOTLID	BENT	1,280.40	905.20
1	REAR BOOTLID "LOGO" EMBLEM	NECESSARY	100.10	58.60
1	REAR BOOTLID "COROLLA ALTIS" EMBLEM	NECESSARY	95.80	60.20
1	REAR BOOTLID "HYBRID" EMBLEM	NECESSARY	96.40	58.20
1	REAR BOOTLID OUTER GARNISH	SERVICEABLE	516.20	-
1	REAR BOOTLID TAILLAMP LH	MTG CRACKED	297.30	297.30
1	REAR BOOTLID INNER TRIM BOARD	SERVICEABLE	272.60	-
1	REAR BOOTLID WEATHERSTRIP	SERVICEABLE	307.40	-
1	REAR TAILLAMP OUTER LH	TO REPAIR SEE LABOUR	456.80	-
1	REAR TAILLAMP OUTER LOWER BRACKET LH	SERVICEABLE	145.70	-
1	REAR BUMPER	BUCKLED	1,854.60	563.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	172.60	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	79.80	-
1	REAR END PANEL (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-1,418.93	-485.63
			4,256.77	1,456.87
<u>SPECIAL NETT ITEMS</u>				
1	REAR BOOTLID ADVERTISING STICKER (SN)	NECESSARY	80.00	60.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	65.00	-
1	REAR BOOTLID INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	300.00	-
			525.00	110.00
<u>LABOUR</u>				
	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST REAR ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF REAR TAILLAMP OUTER LH AND REAR END PANEL.		800.00	350.00
	LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR ACCIDENT AREA.		800.00	400.00

Report Ref No. CS/AIS22004518/Ktcn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	NOT NECESSARY	100.00	50.00
	TO DIAGNOSE FAULT CODE & RESET MEMORY.		120.00	-
	TO TUFF KOTE & UNDERSEAL MATERIALS.		100.00	30.00
	TO CHECK WIRING & ELECTRICAL SYSTEM ETC.		100.00	20.00
			2,020.00	850.00
GRAND TOTAL			6,801.77	2,416.87
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,900.00

Report Ref No. CS/AIS22004518/Ktcn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.