

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004520/EVCQ2**Date:** 25/08/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00006492101

**Claimant Vehicle
No :** SKS6269Y**Insured Vehicle
No :** SLK4366T

Date of Loss: 06/05/2022

Nature of Claim: TP

Claim
No: SNM22D203172/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKS6269Y**

Make & Model: BMW X3, 2.0 (A)

Engine No: A6300900N20B20A

Reg. Date: 28/04/2015 (Man. Year: 2014)

Chassis No: WBAWY920900J00048

Colour: Silver

Odometer: 131880 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 5,406.25 | 4,465.75 | 940.50 | 17.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 5,747.00 | 4,736.00 | 1,011.00 | 17.59 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 11,153.25 | 9,201.75 | 1,951.50 | 17.50 |
| + GST 7.00/7.00% (S\$) | 780.73 | 644.12 | 136.61 | 17.50 |
| Nett Amount (S\$) | 11,933.98 | 9,845.87 | 2,088.11 | 17.50 |

INSPECTION

Date of Assignment: 23/08/2022

Date Inspected: 25/07/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance
Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 24 Aug 2022) |
| Parts: | M1-SUV | BMW X3 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SKS6269Y) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|--------------------------|-----------------|
| 1 | 1 | | *SUNDRIES | Necessary | 150.00 FS | *80.00 FS |
| 2 | 1 | | *BOOTLID | Dented | 1,870.95 FS | *1,899.05 FS |
| 3 | 1 | | *RR BUMPER CARRIER ECE | Not Necessary | 801.80 FS | *- FS |
| 4 | 1 | | *COVER MIDDLE BOTTOM | Not Necessary | 99.95 FS | *- FS |
| 5 | 1 | | *REAR BUMPER CLADDING (PDC/SCHWARZ) | Cut | 209.30 FS | *212.45 FS |
| 6 | 1 | | *REAR BUMPER PANEL PRIMER (PDC) | Dented | 1,517.45 FS | *1,517.45 FS |
| 7 | 1 | | *MODEL LETTERING X3 | Necessary | 65.60 FS | *65.60 FS |
| 8 | 1 | | *(DG) CLEANER R1 (100ML) | Necessary | 26.15 FS | *26.15 FS |
| 9 | 2 | | *(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | Necessary | 263.10 FS | *263.10 FS |
| 10 | 1 | | *(DG/SL) ADHESIVE PRIMER VP 206 (30ML) | Necessary | 27.85 FS | *27.85 FS |
| 11 | 4 | | *EXPANDING NUT | Necessary | 4.00 FS | *4.00 FS |
| 12 | 1 | | *TRUNK LID BADGE | Necessary | 72.85 FS | *72.85 FS |
| 13 | 10 | | *BUMP STOP | Necessary | 33.00 FS | *33.00 FS |
| 14 | 10 | | *EXPANDING RIVET BLACK | Necessary | 14.00 FS | *14.00 FS |
| 15 | 1 | | *THIRD STOPLAMP | Necessary | 250.25 FS | *250.25 FS |
| | | | | | Total Parts (S\$) | 5,406.25 |
| | | | | | | 4,465.75 |

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REPLACE REAR BUMPER TAILGATE AND ATTACHMENTS | New | 2,550.00 | 1,700.00 |
| 2 | TO PAINTING REAR BUMPER AND TAILGATE | New | 2,076.00 | 1,972.00 |
| 3 | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR | New | 574.00 | 545.00 |
| 4 | TO CONDUCT WATER LEAK TESTS | New | 75.00 | 71.00 |
| 5 | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| 6 | TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| 7 | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) | New | 118.00 | 112.00 |
| Gross Labour Cost (\$\$) | | | 5,747.00 | 4,736.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >