

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22004522/KQCQ2**Date:** 14/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00140292100
Claimant Vehicle No :	SLL3997Z	Insured Vehicle No :	YP1203U
Date of Loss:	11/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203285/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL3997Z	Engine No:	2ZR1911351
Make & Model:	TOYOTA WISH, 1.8 X CVT (A)	Chassis No:	JTDGG20W20J006435
Reg. Date:	24/02/2017 (Man. Year: 2017)	Odometer:	92779 km
Colour:	Metallic Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,497.70	1,058.92	2,438.78	69.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	700.00	390.00	35.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,587.70	1,758.92	2,828.78	61.66
+ GST 8.00/8.00% (S\$)	367.02	140.71	226.31	61.66
Nett Amount (S\$)	4,954.72	1,899.63	3,055.09	61.66

INSPECTION

Date of Assignment:	19/05/2022	
Date Inspected:	17/05/2022 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Different 1 cents -Finalise confirm amount:\$1,758.93

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Apr 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL3997Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,037.80 FL	*- FL
2	1		*FRONT BONNET EMBLEM	Necessary	67.80 FL	*67.80 FL
3	1		*FRONT BONNET LOCK	Repair	119.10 FL	*- FL
4	1		*FRONT BONNET RUBBER	Serviceable	47.30 FL	*- FL
5	6		*FRONT BONNET INSULATOR CLIPS	Not Necessary	21.00 FL	*- FL
6	1		*FRONT BONNET HINGE RH	Repair	71.50 FL	*- FL
7	1		*HEADLAMP RH	Cut	1,344.10 FL	*1,344.10 FL
8	1		*FRONT BUMPER	Repair	626.70 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	66.60 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Not Necessary	4.80 FL	*- FL
11	1		*FRONT FENDER RH	Repair	1,049.00 FL	*- FL
12	1		*FRONT FENDER COWLING RH	Serviceable	183.10 FL	*- FL
13	8		*FRONT FENDER COWLING CLIPS	Not Necessary	24.80 FL	*- FL
					Sub Total (\$\$)	4,663.60 1,411.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,165.90 352.98
					Total Parts (\$\$)	3,497.70 1,058.92

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO DISMANTLE ALL DAMAGED PARTS ,TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	400.00	280.00
3	TO SPRAY BONNET ,FRONT BUMPER,FRONT FENDER RH	New	650.00	400.00
Gross Labour Cost (S\$)			1,090.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >