



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 2343Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SET FRONT BUMPER ASSY	WARPED	1,420.00	521.00
1	FRONT BUMPER UPPER GRILLE	NOT NECESSARY	650.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	580.00	-
1	FRONT BUMPER SHOCK ABSORBER FOAM	CRACKED	440.00	83.00
1	FRONT BUMPER TOW CAP	REUSE	250.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	480.00	-
1	FRONT HEADLAMP RH	CUT	1,800.00	1,800.00
1	FRONT FOG LAMP RH	NOT NECESSARY	690.00	-
1	FRONT WHEEL BEARING HUB RH	NOT NECESSARY	720.00	-
1	FRONT WHEEL SHOCK ABSORBER RH	NOT NECESSARY	625.00	-
1	FRONT WHEEL CAP RH	CUT	280.00	190.00
1	FRONT WIPER TANK ASSY	NOT NECESSARY	670.00	-
	LESS 25% DISCOUNT		-2,151.25	-648.50
			6,453.75	1,945.50
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	100.00	30.00
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	100.00	-
1	FRONT WHEEL STEEL RIM RH (SN) (CUT)	NOT CONSISTENT WITH THE IMPACT	650.00	-
1	FRONT WHEEL TYRE RH (SN)	NOT NECESSARY	180.00	-
			1,030.00	30.00
<u>LABOUR</u>				
	TO CUT / WELD, STRAIGHTEN AFFECTED AREAS AND REPLACE DAMAGED PARTS.		2,800.00	400.00
	TO PUTTY AND SPRAY PAINTING THE AFFECTED AREAS. JOB ALLOWANCE.		2,800.00	450.00
	TO REMOVE AND INSTALL FRONT GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	280.00	-
	TO CHECK FRONT & LIGHTING AND WIRING.		280.00	30.00
	TO APPLY ANTI RUST PROOFING TO THE AFFECTED AREAS.	NOT NECESSARY	380.00	-
	TO REMOVE AND INSTALL HEADLAMP AND FOG LAMP.	NOT NECESSARY	280.00	-

Report Ref No. CS3/LPC22000632/Vty3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL WIPER TANK.	NOT NECESSARY	280.00	-
	TO REMOVE AND INSTALL DAMAGED WHEEL COMPONENTS.	NOT NECESSARY	300.00	-
	TO REMOVE AND INSTALL FRONT BUMPER GRILLES.	NOT NECESSARY	280.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	380.00	-
	TO CONDUCT CHASSIS ALIGNMENT.	NOT NECESSARY	380.00	-
	TO REMOVE AND INSTALL FRONT BUMPER ASSY.	NOT NECESSARY	280.00	-
			8,720.00	880.00
GRAND TOTAL			16,203.75	2,855.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS3/LPC22000632/Vty3e2-1

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.