

J&M CONSULTANCY PTE LTD

11 Changi South Lane #02-08
ONN WAH BUILDING Singapore 486154
Company Reg No: 202125502E
Tel: 6214-0474 Fax: 6384-5205

VEHICLE INSPECTION REPORT

To: Fresh Cars Pte Ltd

Date : 14 March 2022

C/o: A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Our ref : ATEC/03/0005/JM

Accident Date : 13 January 2022
Inspection Date : 18 January 2022
Repairer Name : A-Tec Automotive Pte Ltd
8 Kaki Bukit Avenue 4
#04-20 Premier @ Kaki Bukit, Singapore 415875

Type of Survey : Third party

PARTICULARS OF VEHICLE

Registration No : SLK 2343 Y
Make / Model : Toyota / Prius Hybrid
Chassis No : JTDKB3FU403544059
Engine No : 2ZRR991638

Year / Capacity : 2016 / 1797 cc
Colour : White
Mileage : 169,560 km

CONDITION OF TYRES

	Make	Size	Thread Balance
Front Nearside :	Kumho	195/65/ R16	80%
Front Offside :	Kumho	195/65/ R16	80%
Rear Nearside :	Kumho	195/65/ R16	80%
Rear Offside :	Kumho	195/65/ R16	80%

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the front bumper
(Details refer to the photographs attached)

Enclosed number of photographs: **49** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SLK 2343 Y

Our Ref No: ATEC/03/0005/JM

RECOMMENDATIONS

Under normal circumstances, the repair period would be about 7 (Seven) working days.

Qty	Description	Condition	Repairer's Estimate	Revised Amount
-----	-------------	-----------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Front bumper assy (1 set)	Warped	\$ 1,420.00	\$ 1,420.00 ⁵²¹
1	Front bumper upper grille	Warped	\$ 650.00	\$ 650.00 ^{XNN}
1	Front bumper lower grille	Warped	\$ 580.00	\$ 580.00 ^{XNN}
1	Front bumper shock absorber foam	Cracked	\$ 440.00	\$ 440.00 ⁸³
1	Front bumper tow cap	Reuse	\$ 250.00	\$ -
1	Front support panel top garnish	Warped	\$ 480.00	\$ 480.00 ^{XNN}
1	Front headlamp RH	Warped ^{CUT}	\$ 1,800.00	\$ 1,800.00 [✓]
1	Front fog lamp RH	Cracked	\$ 690.00	\$ 690.00 ^{XNN}
1	Front wheel bearing hub RH	Bent	\$ 720.00	\$ 720.00 ^{XNN}
1	Front wheel shock absorber RH	Bent	\$ 625.00	\$ 625.00 ^{XNN}
1	Front wheel cap RH	Cut	\$ 280.00	\$ 280.00 ¹⁹⁰
1	Front wiper tank assy	Warped	\$ 670.00	\$ 670.00 ^{XNN}
			\$ 8,605.00	\$ 8,355.00
Less 25%			\$ 2,151.25	\$ 2,088.75
			\$ 6,453.75	\$ 6,266.25

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	Necessary	\$ 100.00	\$ 100.00 ³⁰
1	Front support panel top garnish clips (1 set)	Necessary	\$ 100.00	\$ 100.00 ^{XNN}
1	Front wheel steel rim RH	Cut	\$ 650.00	\$ 650.00 ^{XNC}
1	Front wheel tyre RH	Torn	\$ 180.00	\$ 180.00 ^{XNN}
			\$ 1,030.00	\$ 1,030.00
Total parts			\$ 7,483.75	\$ 7,296.25

J&M CONSULTANCY PTE LTD

Vehicle Registration No: SLK 2343 Y

Our Ref No: ATEC/03/0005/JM

S/No	Description	Repairer's Estimate	Revised Amount
------	-------------	---------------------	----------------

Total cost of parts c/f

\$ 7,483.75

\$ 7,296.25

LABOUR

1	To cut, weld, straighten affected areas and replace damaged parts.	\$ 2,800.00	\$ 2,600.00 400
2	To putty and spray painting the affected areas. Job Allowance.	\$ 2,800.00	\$ 2,600.00 450
3	To remove and install front garnish and trim to facilitate the repair.	\$ 280.00	\$ 260.00 X
4	To check front & lighting and wiring.	\$ 280.00	\$ 260.00 30
5	To apply anti rust proofing to the affected areas.	\$ 380.00	\$ 360.00 X
6	To remove and install front bumper assy.	\$ 280.00	\$ 260.00 X
7	To remove and install headlamp and fog lamp.	\$ 280.00	\$ 260.00 X
8	To remove and install wiper tank.	\$ 280.00	\$ 260.00 X
9	To remove and install damaged wheel components.	\$ 300.00	\$ 280.00 X
10	To remove and install front bumper grilles.	\$ 280.00	\$ 260.00 X
11	To conduct wheel alignment	\$ 380.00	\$ 360.00 X
12	To conduct chassis alignment	\$ 380.00	\$ 360.00 X

Grand Total:

\$ 16,203.75

\$ 15,416.25

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 12,300**

4 days