



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHARACTERIST LLC 190 MIDDLE ROAD #15-01A FORTUNE CENTRESINGAPORE 188979			Ref: CS/LAW22004531/Aqce2	
			Date: 05/07/2022	
			Code: L057	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
Insured Veh.	XE 345U		Veh. Inspected	PC 4776M
Policy No.			Coverage (\$)	0.00
Claim No.	MC/MC 4483/2021		Excess (\$)	0.00
Assign From	KIRAN KAUR		Assign Date	13/05/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV350		c.c	2488
Engine No.	HIDDEN		Year of Reg.	2016
Chassis No.	JN1UC4E26Z0001766		Colour	SILVER
Odometer	277018 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		195 R15C	FALKEN	6 mm
L/H Front Tyre		195 R15C	FALKEN	6 mm
R/H Rear Tyre		195 R15C	FALKEN	6 mm
L/H Rear Tyre		195 R15C	FALKEN	6 mm
<b>4. Description of Damages</b>				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	11/09/2019		Inspection Date	18/05/2022
Survey held at	BLK 51 DEFU LANE 9 SINGAPORE 539291			
Repairer	AUTOMOBILE HUB ENTERPRISE			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>10 Working Days</b>	