

AJAX

Inspection Services Pte Ltd

INSPECTION REPORT

Automobile Hub Enterprise

1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit Singapore 417883

Assign Date:	18/09/2019	Inspection Date:	18/09/2019	TP Report Date:	11/09/2019
Accident Date:	11/09/2019	TP Policy No:	DMB1SN3027851900	Our Ref:	AVS2019-20778/PN
Place of Inspection:	Automobile Hub Enterprise 1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit Singapore 417883			Your Ref:	PC4776M
				Claimant:	N & J Shipyard Services

Description of Vehicle:

Veh. No:	PC4776M	Make/Model:	Nissan NV350 HR Microbus 2.5 4DR 5AT ABS D/AB		
Colour:	Silver	Engine No:	YD25348198A	Sum Insured (\$\$):	Market Value
Engine Capacity:	2,488 cc	Chassis No:	JN1UC4E26Z0001766	Mkt Value (\$\$):	\$42,000.00
meter:	81937	Reg. Date:	28/04/2016		


Condition of Vehicle:

General:	Fair	Modification:	No	Steering:	Serviceable
Air-Conditioner:	Yes	Radio/Cassette/CD:	Yes	Wing Mirror:	Yes
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Fair
Tyre Make:	Falken			Front Right Side:	5mm
Front Tyre Size:	195R15C	Front Left Side:	5mm	Rear Right Side:	5mm
Rear Tyre Size:	195R15C	Rear Left Side:	5mm		

Description of Damage:

The damage was found on the right portion. The right side panel and rear fender, right front side window, right C and D pillar, roof panel were among other parts affected.

Point of Impact:



Adjuster:

Patrick Ng
Motor Appraiser

COMPLETED 17 OCT 2019

Date

Note: This report is confidential and solely for the use of the client. The inspection was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				Our Ref: AVS2019-20778/PN	
PC4776M					
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Side panel o/s	Damaged	1,895.00	1,895.00 ✓
2	1	Rear fender o/s	Repair	1,379.00	--
3	1	C pillar o/s	Bent	943.00	943.00 ✓
4	1	C pillar inner trim o/s	Damaged	157.00	157.00 ✓
5	1	D pillar o/s <i>Regis</i>	Bent	943.00	943.00 X
6	1	D pillar inner trim o/s <i>Regis</i>	Damaged	157.00	157.00 X
7	1	Rear 2nd row seat o/s	Torn	1,117.00	1,117.00 <i>SW (SW)</i>
8	1	Window glass front o/s	Broken	1,415.00	1,415.00 ✓
9	1	Window glass front moulding o/s	Necessary	133.00	133.00 ✓
10	1	Window glass centre o/s	Broken	913.00	913.00 ✓
11	1	Window glass centre moulding o/s	Necessary	117.00	117.00 ✓
12	1	Window glass rear o/s	Broken	1,415.00	1,415.00 ✓
13	1	Window glass rear moulding o/s	Necessary	133.00	133.00 ✓
14	1	Roof panel	Repair	2,637.00	--
15	1	Side panel trim board o/s	Not necessary	479.00	--
16	1	Rear fender trim board o/s	Not necessary	553.00	--
Sub Total:				14,386.00	9,338.00
<i>7091</i> Discount (less 30%) <i>4963-70</i> <i>S-N: 500</i>				0.00	2,801.40
				14,386.00	6,536.60

Special Nett Items					
1	6	C pillar inner trim clips o/s	Necessary	27.00	20.00 ✓
2	6	D pillar inner trim clips o/s	Necessary	27.00	20.00 ✓
3	1	Window glass front sealant o/s	Necessary	120.00	100.00 <i>60</i>
4	1	Window glass front solar film o/s	Necessary	180.00	150.00 ✓
5	1	Window glass centre sealant o/s	Necessary	120.00	100.00 <i>40</i>
6	1	Window glass centre solar film o/s	Necessary	140.00	120.00 <i>80</i>
7	1	Window glass rear sealant o/s	Necessary	120.00	100.00 <i>60</i>
8	1	Window glass rear solar film o/s	Necessary	180.00	150.00 ✓
9	28	Roof lining clips	Necessary	126.00	80.00 ✓
10	1	Side panel trim board clips o/s	Necessary	54.00	40.00 ✓

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:				Our Ref: AVS2019-20778/PN	
PC4776M					
No.	Qty	Description of Parts	Condition	Repairer's Estimate S\$	Our Recommendation S\$
11	1	Rear fender trim board clips o/s	Necessary	54.00	40.00 ✓
12	1	Sundries	Necessary	50.00	30.00 ✓
710				Sub Total:	1,198.00
				Total Parts Price:	15,584.00
					950.00
					7,486.60

Labour Cost			
1	To dismantle/ renew accident damaged portion, to panel beat, reshape, straighten, orientate and align repair/ replacement parts.	3,000.00	2,800.00
2	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check functions.	100.00	60.00
3	To remove and replace rear 2nd row seats, check alignment.	150.00	100.00
4	To remove and refit interior upholstery, inner trim, inner garnish, mouldings, roof lining to facilitate repair.	300.00	200.00
5	To remove broken glass fragments to facilitate repair.	100.00	80.00
6	Supply spray paint material and necessary items to respray roof panel, side panel/s, C pillar, D pillar, rear fender and other affected area/ panel.	2,000.00	1,800.00
7	To rust proof all affected portions after repair.	200.00	100.00
		2260	
Sub Total:		5,850.00	5,140.00
Grand Total:		21,434.00	12,626.60

Recommendation and Conclusion:

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimate repair cost is S\$21,434.00. The repairer has agreed to undertake the repairs at our adjusted part by part basis amount of S\$10,100.00.

We have not authorised the repair. Under normal circumstances, estimated sixteen (16) working days are required to repair

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.

The inspection was conducted entirely on a "Without Prejudice" basis.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R