

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22004535/APA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210082161
Claimant Vehicle No :	SMK1871J	Insured Vehicle No :	SNB1509S
Date of Loss:	13/05/2022	Nature of Claim:	TP
		Claim No:	7933387880SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK1871J	Engine No:	PE21265356
Make & Model:	MAZDA 6, 2.0 SEDAN STANDARD 2WD (A)	Chassis No:	JM6GL1072K0314377
Reg. Date:	29/03/2019 (Man. Year: 2019)	Odometer:	61832 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,839.52	2,759.20	5,080.32	64.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,170.00	1,350.00	1,820.00	57.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,009.52	4,109.20	6,900.32	62.68
+ GST 7.00/7.00% (\$\$)	770.67	287.64	483.03	62.68
Nett Amount (\$\$)	11,780.19	4,396.84	7,383.35	62.68
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		38.45		
Nett Liability (\$\$)		5,035.29		
Global Sum Settlement (\$\$)		5,000.00		

INSPECTION

Date of Assignment:	13/05/2022	
Date Inspected:	17/05/2022	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,354.30 FL	*1,047.00 FL
2	2		*REAR BUMPER TOW COVER	Deformed	160.20 FL	*35.00 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	586.90 FL	*586.90 FL
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	190.20 FL	*190.20 FL
5	1		*REAR BUMPER O/S & N/S REFLECTOR	O/S Cracked	266.00 FL	*133.00 FL
6	1		*REAR BUMPER RETAINER MIDDLE	Not Necessary	134.60 FL	*- FL
7	1		*REAR BOOT COVER	Repair	1,406.40 FL	*- FL
8	1		*REAR BOOT COVER WEATHERSTRIP	Not Necessary	225.10 FL	*- FL
9	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	166.00 FL	*- FL
10	1		*REAR BOOT COVER MAZDA 6 EMBLEM	Necessary	73.40 FL	*73.40 FL
11	1		*REAR BOOT COVER SKY ACTIV EMBLEM	Necessary	74.30 FL	*74.30 FL
12	1		*REAR BOOT COVER EMBLEM	Necessary	85.40 FL	*85.40 FL
13	1		*REAR BOOT COVER O/S REFLECTOR	Not Necessary	856.60 FL	*- FL
14	1		*REAR BOOT COVER LOCK (UPPER)	Not Necessary	475.50 FL	*- FL
15	1		*REAR BOOT COVER LOCK (LOWER)	Not Necessary	87.60 FL	*- FL
16	1		*REAR END PANEL	Dented	636.50 FL	*636.50 FL
17	1		*REAR END PANEL INNER TRIM	Deformed	274.80 FL	*274.80 FL
18	1		*REAR O/S TAIL LAMP	Not Necessary	1,772.70 FL	*- FL
19	1		*SET REAR REVERSE SENSOR	Damaged	688.32 FS	*200.00 FS
20	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 FL	*- FL
22	8		*REAR END PANEL INNER TRIM CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,604.82	3,386.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,765.30	627.30
Total Parts (S\$)	7,839.52	2,759.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE ,STRAIGHTEN & WELDING	New	1,400.00	600.00
2	TO SPRAY PAINTING	New	1,200.00	600.00
3	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	60.00
4	TO REMOVE & REPLACE REAR BOOT LID	New	80.00	0.00
5	TO CHECK FOR FAULT CODE AND RESETTNG	New	250.00	0.00
6	TO CHECK WIRING	New	80.00	30.00
7	TO RESEAL ANTI RUST	New	80.00	60.00
Gross Labour Cost (\$\$)			3,170.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >