

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	HSBC LIFE (SING	APORE) PTE LTD		Ref:	CC4/ASM22004537/Apa3q2
	10 MARINA BOULE #48-01 MARINA BA 2SINGAPORE 018	AY FINANCIAL CENTRE TOWER		Date:	26/04/2023
	ATTN:CYNTHIA			Code:	HSB
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 8086P	Veh. Inspected		SLE 9520M
	Policy No.	P2465714	Coverage (\$)		0.00
	Claim No.	S2M040Y3	Excess (\$)		0.00
	Assign From		Assign Date		13/05/2022
2. Vehicle Particulars & Condition					
	Make & Model	KIA CERATO FORTE	c.c		1591
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	KNAFW411MA5274862	Colour		BRONZE
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/55 R16	PIRELLI		6 mm
	L/H Front Tyre	205/55 R16	PIRELLI		6 mm
	R/H Rear Tyre	205/55 R16	PIRELLI		6 mm
	L/H Rear Tyre	205/55 R16	PIRELLI		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	11/05/2022	Inspection Date	9	13/05/2022
	Survey held at	KANG CAR REPAIRERS PTE LT	ΓD		
		NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 17 Working Days				