

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	List Price		
1	1 PC BONNET	1,056.00	
2	2 PCS BONNET HINGE	132.00	
3	1 PC BONNET RUBBER LONG	31.40	
4	1 PC BONNET RUBBER SHORT	29.60	
5	1 PC BONNET LOCK	146.70	
6	1 PC FRT FENDER RH	460.80	
7	1 PC FRT WHEEL HOUSING RH	966.20	
8	1 PC FRT SUPPORT PANEL	627.10	
9	1 PC FRT GRILLE	285.10	
10	1 PC FRT GRILLE EMBLEM	50.20	
11	1 PC HEADLAMP RH	743.80	
12	1 PC HEADLAMP LH	743.80	
13	1 PC FRT BUMPER	784.80	
14	1 PC FRT BUMPER REINFORCEMENT	294.40	
15	2 PCS FRT BUMPER SIDE RETAINER	78.20	
16	1 PC FRT BUMPER SPONGE	101.80	
17	1 PC FRT FOG LAMP RH	277.10	
18	1 PC FRT FOG LAMP COVER RH	99.60	
19	1 PC FRT FOG LAMP LH	277.60	
20	1 PC FRT FOG LAMP COVER LH	99.60	
21	1 PC FRT BUMPER GRILLE	166.20	
22	1 PC FRT BUMPER LOWER SPOILER	281.70	
23	1 PC FRT NUMBER PLATE BASE	78.40	
24	1 PC FRT WINDSCREEN GLASS	1,231.40	
25	1 PC FRT WINDSCREEN MOULDING	99.40	
26	1 PC FRT WIPER PANEL GARNISH	187.00	
27	1 PC FRT WIPER PANEL GARNISH RUBBER	54.40	
28	1 PC FRT WIPER PANEL RH CORNER GARNISH	38.60	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
29	1 PC FRT FENDER LH	460.80	
30	1 PC FRT FENDER COWLING LH	169.30	
31	1 PC FRT DOOR RH	872.20	
32	1 PC FRT DOOR SIDE MIRROR RH	468.60	
33	1 PC FRT DOOR RH FRAME BLACK STICKER	39.50	
34	1 PC FRT DOOR OUTER HANDLE RH	101.80	
35	1 PC FRT SHOCK ABSORBER RH	358.50	
36	1 PC FRT LOWER ARM RH	391.80	
37	1 PC FRT KNUCKLE ARM RH	385.00	
38	1 PC FRT BEARING RH	85.40	
39	1 PC FRT WHEEL HUB RH	232.00	
40	1 PC FRT RH BRAKE DISC ROTOR	312.40	
41	1 PC FRT RH BRAKE DISC ROTOR PANEL	112.80	
42	1 PC FRT BRAKE PIPE RH	68.10	
43	1 PC FRT RH BRAKE CALIPER	566.90	
44	1 PC ANTI ROLL BAR	280.00	
45	1 PC ANTI ROLL BAR LINKAGE	91.40	
46	1 PC FRT DRIVE SHAFT RH	1,086.80	
47	1 PC FRT CROSSMEMBER	1,271.60	
48	1 PC STEERING RACK & PINION	2,263.70	
49	1 PC ENGINE MOUNTING RH	239.80	
50	1 PC FRT ENGINE MOUNTING RH BRACKET	133.90	
51	1 PC POWER STEERING FLUID TANK	176.00	
52	1 PC POWER STEERING FLUID TANK PIPE	91.40	
53	1 PC FRT POWER STEERING PUMP	754.60	
54	1 PC ENGINE MOUNTING LH	269.70	
55	1 PC ENGINE MOUNTING LH BRACKET	138.70	
56	1 PC FRT LOWER ARM TIE ROD	81.20	
57	1 PC POWER STEERING PIPE	122.30	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
58	1 PC RADIATOR	701.80	
59	1 PC FRT WIPER TANK	177.60	
60	1 PC FRT WIPER TANK MOTOR	100.40	
61	1 PC AIRCON CONDENSER	773.30	
62	1 PC FRT AIRCON DISCHARGE PIPE	299.90	
63	1 PC AIRCON RECEIVER PIPE	243.50	
		23,345.60	
	Less 20%	4,669.12	18,676.48
	Special Net		
64	1 SET FRT FENDER COWLING CLIPS RH	60.00	
65	1 SET FRT GRILLE CLIPS	40.00	
66	1 SET FRT BUMPER GRILLE CLIPS	40.00	
67	1 SET FRT BUMPER LOWER SPOILER CLIP	40.00	
68	1 PC FRT NUMBER PLATE	50.00	
69	1 PC FRT WINDSCREEN GUM	60.00	
70	1 PC FRT WINDSCREEN SEAL	60.00	
71	1 SET FRT FENDER COWLING CLIPS LH	40.00	
72	1 PC FRT SPORTS RIM RH	800.00	
73	1 PC FRT TYRE RH	300.00	
74	1 PC POWER STEERING OIL	80.00	
		1,570.00	1,570.00
	Labour		
75	1 TO CHECK WIRING	50.00	
76	1 TO REFILL AIRCON GAS	120.00	
77	1 TO REMOVE AND REFIT FRONT WINDSCREEN	120.00	
78	1 PC TO REMOVE AND REFIT RH DOOR GLASS	100.00	
79	1 TO REMOVE AND REFIT ENGINE	800.00	
80	1 TO REMOVE AND REFIT UNDERCARRIAGE	580.00	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 11/05/2022
TP Veh Reg No: SHC8086P

Estimate No: EST2200151

Date: 13 May 2022

Veh Reg No: SLE9520M

Make/Model: KIA CERATO FORTE
1.6SX AT SBS D/AB
2WD 4DR

Chasis No: KNAFW411MA5274862

Reg. Date: 14/09/2010

Your Ref No: SHC8086P

Estimate Repair Cost to Vehicle No :SLE9520M

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
81	1 TO CHECK WHEEL ALIGNMENT	120.00	
82	1 TO SPRAY PANEL SEALANT	150.00	
83	1 (FRONT) TO SPRAY PAINTING	2,000.00	
84	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	2,800.00	
		6,840.00	6,840.00
		Total	S\$ 27,086.48
		Add GST @ 7%	1,896.05
		Total Amount Payable	<u>S\$ 28,982.53</u>

TOTAL: SINGAPORE DOLLAR TWENTY EIGHT THOUSAND NINE HUNDRED EIGHTY TWO AND CENTS FIFTY THREE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE