

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22004540/APA3Q2**Date:** 11/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100371766
Claimant Vehicle No :	SKU2793R	Insured Vehicle No :	GBC332C
Date of Loss:	10/05/2022	Nature of Claim:	TP
		Claim No:	0719031967SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2793R	Engine No:	CZD206628
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8U0FR048639
Reg. Date:	15/07/2015 (Man. Year: 2015)	Odometer:	133627 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,088.00	4,393.76	3,694.24	45.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,052.00	3,022.00	4,030.00	57.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,140.00	7,415.76	7,724.24	51.02
+ GST 8.00/8.00% (S\$)	1,211.20	593.26	617.94	51.02
Nett Amount (S\$)	16,351.20	8,009.02	8,342.18	51.02
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,211.02		

INSPECTION

Date of Assignment:	18/05/2022		
Date Inspected:	18/05/2022	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,682.00 FS	*1,345.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	129.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Deformed	979.00 FS	*783.20 FS
4	1		*REAR BUMPER DIFUSSER	Deformed	786.00 FS	*628.80 FS
5	1		*REAR BUMPER TOWING EYE - LH	Deformed	48.00 FS	*38.24 FS
6	1		*REAR BUMPER TAIL LIGHT - LH	Cut	512.00 FS	*409.60 FS
7	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	693.00 FS	*- FS
8	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	112.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
			(NPA)			
10	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	6.00 FS	*- FS
11	1		*REAR PACKING ADHESIVE	Necessary	21.00 FS	*16.72 FS
12	1		*AUDI EMBLEM	Necessary	144.00 FS	*114.80 FS
13	1		*Q3 EMBLEM	Necessary	104.00 FS	*82.80 FS
14	1		*TFSI EMBLEM	Necessary	104.00 FS	*82.80 FS
15	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,114.00 FS	*891.20 FS
16	1		*REAR SILENCER	Not Necessary	1,171.00 FS	*- FS
17	1		*REAR SILENCER DUAL CLIP	Not Necessary	66.00 FS	*- FS
18	2		*REAR SILENCER RETAINING RING - CENTER / RH	Not Necessary	40.00 FS	*- FS
19	1		*REAR SILENCER RETAINING BRACKET - LH	Not Necessary	77.00 FS	*- FS
20	1		*EXHAUST TAILPIPE CHROME TRIM	Not Necessary	0.00 FS	*- FS
			(NPA)			
21	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					8,088.00	4,393.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER, REAR BUMPER LOWER SPOILER,REAR LID, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS	New	4,500.00	2,050.00
4	TO RENEW LHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,052.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >