

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004544/APA3Q2**Date:** 20/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700092517
Claimant Vehicle No :	GBB8842A	Insured Vehicle No :	SLV9008L
Date of Loss:	10/05/2022	Nature of Claim:	TP
		Claim No:	3575340423SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB8842A		
Make & Model:	NISSAN CABSTAR, 3.0 (M)	Engine No:	ZD30255871K
Reg. Date:	10/08/2010 (Man. Year: 2010)	Chassis No:	JN1SC2F24Z0801505
Colour:	Silver	Odometer:	351781 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	OHTSU 6 mm	Rear Left Side:	GREEN-MAX 6 mm
Front Right Side:	OHTSU 6 mm	Rear Right Side:	GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,427.87	4,010.21	5,417.66	57.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	1,730.00	4,250.00	71.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,407.87	5,740.21	9,667.66	62.74
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	15,407.87	4,600.00	10,807.87	70.15
+ GST 7.00/7.00% (S\$)	1,078.55	322.00	756.55	70.15
Nett Amount (S\$)	16,486.42	4,922.00	11,564.42	70.15
+ Loss of Use (5.0 x S\$90.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,379.45		
Global Sum Settlement (S\$)		5,370.00		

INSPECTION

Date of Assignment:	11/05/2022	
Date Inspected:	11/05/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	1,388.40 FL	*1,388.40 FL
2	1		*REAR TAILGATE LOCK	Damaged	199.38 FL	*199.38 FL
3	1		*REAR TAILGATE LOWER BRACKET	Bent	197.60 FL	*197.60 FL
4	2		*REAR TAILGATE LOWER BRACKET STOPPER	Missing	43.80 FL	*43.80 FL
5	1		*REAR NUMBER PLATE LAMP	Not Necessary	94.30 FL	*- FL
6	1		*REAR NUMBER PLATE BRACKET	Bent	267.10 FL	*267.10 FL
7	2		*REAR TAILLAMP (RH)	Cracked	267.90 FL	*267.90 FL
8	2		*REAR TAILLAMP BRACKET (RH)	Bent	149.80 FL	*149.80 FL
9	1		*REAR SIDE TAILGATE RH	Repair	1,654.60 FL	*- FL
10	1		*REAR END LOWER PANEL	Dented	889.60 FL	*495.00 FL
11	1		*REAR EXHAUST PIPE	Not Necessary	698.20 FL	*- FL
12	1		*REAR EXHAUST PIPE MOUNTING /BRACKET	Not Necessary	58.60 FL	*- FL
13	1		*REAR SPARE TYRE LOCK BRACKET	Not Necessary	237.10 FL	*- FL
14	1		*REAR SPARE TYRE LOCK NUT	Damaged	231.60 FL	*231.60 FL
15	3		*TAILGATE HINGE	Bent	254.10 FL	*254.10 FL
16	1		*REAR NUMBER PLATE WITH CASING	Bent	60.00 FS	*30.00 FS
17	1		*REAR STEP PANEL	Bent	550.00 FS	*250.00 FS
18	1		*REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
19	1		*REAR STCIKER 70 KM/H	Necessary	35.00 FS	*15.00 FS
20	1		*REAR STCIKER NISSAN	Necessary	35.00 FS	*35.00 FS
21	1		*REAR STCIKER CABSTAR	Necessary	35.00 FS	*35.00 FS
22	1		*REAR CHASSIS FRAME CROSS MEMBER	Not Necessary	350.00 FS	*- FS
23	1		*REAR TAILGATE COMPANY STICKER	Necessary	550.00 FS	*300.00 FS
24	1		*REAR CARGO PLATFORM PLY WOOD	Not Necessary	400.00 FS	*- FS
25	12		*REAR FLOOR PANEL MOUNTING	Not Necessary	1,020.00 FS	*- FS
26	12		*REAR FLOOR PANEL RUBBER MOUNTING RUBBER	Not Necessary	144.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,091.08	4,359.68
- List Item Discount on L Items 10.00/10.00% (\$\$)	663.21	349.47
Total Parts (\$\$)	9,427.87	4,010.21

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,500.00	800.00
2	LABOUR FOR SPRAYPAINTING	New	1,200.00	650.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & REFIX REAR FLOOR PANEL TO FACILITATE THE REPAIR OF REAR BOTH CHASSIS FRAME	New	800.00	0.00
5	LABOUR FOR REPAIR & STRAIGHTEN BOTH REAR CHASSIS FRAME	New	600.00	200.00
6	TO APPLY RUST PROOF/TUFF COAT ON ACCIDENT AREAS	New	300.00	50.00
7	LABOUR FOR REMOVE & RENEW REAR CARGO PANEL	New	1,200.00	0.00
8	LABOUR FOR REMOVE & RENEW REAR PLY WOOD	New	300.00	0.00
Gross Labour Cost (\$\$)			5,980.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >