

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004545/AYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486563
Claimant Vehicle No :	SKA5715C	Insured Vehicle No :	SLG8366M
Date of Loss:	09/05/2022	Nature of Claim:	TP
		Claim No:	3441658857SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA5715C	Engine No:	L13Z11035483
Make & Model:	HONDA JAZZ, 1.3 L (A)	Chassis No:	JHMGE68509S235457
Reg. Date:	15/03/2011 (Man. Year: 2009)	Odometer:	142563 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,828.88	4,933.60	1,895.28	27.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	3,050.00	1,270.00	29.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,148.88	7,983.60	3,165.28	28.39
Approved Total (Overridden) (S\$)		6,400.00		
(S\$)	11,148.88	6,400.00	4,748.88	42.60
+ GST 8.00/8.00% (S\$)	891.91	512.00	379.91	42.60
Nett Amount (S\$)	12,040.79	6,912.00	5,128.79	42.60
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,814.00		

INSPECTION

Date of Assignment:	11/05/2022	
Date Inspected:	11/05/2022 Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	844.10 FL	*844.10 FL
2	2		*BOOT LID HINGE	Not Necessary	124.00 FL	*- FL
3	1		*BOOT LID JAZZ EMBLEM	Necessary	48.80 FL	*48.80 FL
4	1		*BOOT LID LOGO	Not Necessary	50.20 FL	*- FL
5	1		*BOOT LID LOCK	Damaged	189.50 FL	*189.50 FL
6	1		*BOOT LID LOCK CHECKER	Not Necessary	38.90 FL	*- FL
7	1		*BOOT LID TRIM	Cracked	177.20 FL	*177.20 FL
8	1		*BOOT LID RUBBER	Cut	182.40 FL	*182.40 FL
9	2		*REAR NUMBER PLATE LAMP	Not Necessary	124.80 FL	*- FL
10	1		*REAR WINDSCREEN RUBBER	Necessary	120.50 FL	*120.50 FL
11	1		*REAR FENDER LH	Repair	786.90 FL	*- FL
12	1		*REAR FENDER TRIM LH	Deformed	286.50 FL	*286.50 FL
13	1		*REAR FENDER TRIM RH	Deformed	286.50 FL	*286.50 FL
14	1		*REAR PANEL	Distorted	496.50 FL	*496.50 FL
15	1		*REAR PANEL TRIM	Deformed	166.80 FL	*166.80 FL
16	1		*SPARE TYRE PANEL	Buckled	737.00 FL	*737.00 FL
17	1		*SPARE TYRE PANEL SPONGE	Cracked	236.80 FL	*236.80 FL
18	1		*REAR SPARE TYRE HARDBOARD	Deformed	289.60 FL	*289.60 FL
19	1		*TAIL LAMP LH	Cracked	366.40 FL	*288.00 FL
20	1		*TAIL LAMP - RH	Cut	366.40 FL	*288.00 FL
21	1		*REAR BUMPER	Deformed	497.70 FL	*497.70 FL
22	2		*REAR BUMPER SIDE RETAINER	Necessary	93.60 FL	*93.60 FL
23	1		*SET BOOTLID TRIM CLIPS	Necessary	60.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
25	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*30.00 FS
26	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
27	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
28	1		*SET REAR FENDER TRIM CLIPS LH	Necessary	60.00 FS	*30.00 FS
29	1		*SET REAR FENDER TRIM CLIPS RH	Necessary	60.00 FS	*30.00 FS
30	1		*REAR FENDER LH SIDE GLASS SEAL	Not Necessary	60.00 FS	*- FS
31	1		*REAR FENDER LH SIDE GLASS SEALANT	Not Necessary	60.00 FS	*- FS
32	1		*SET REAR PANEL TRIM CLIPS	Necessary	30.00 FS	*20.00 FS
33	1		*REAR BUMPER LOWER SPOILER	Damaged	600.00 FS	*550.00 FS
34	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,131.10	5,979.50
- List Item Discount on L Items 20.00/20.00% (S\$)	1,302.22	1,045.90
Total Parts (S\$)	6,828.88	4,933.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT REAR BOOTLID SPOILER	New	80.00	0.00
3	TO REMOVE AND REFIT THIRD BRAKE LIGHT	New	80.00	0.00
4	TO REMOVE AND REFIT REAR VIEW CAMERA	New	80.00	50.00
5	TO REMOVE AND REFIT REVERSE CAMERA	New	80.00	50.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO REMOVE AND REFIT REAR INNER TRIM	New	120.00	80.00
8	TO REMOVE AND REFIT PETROL TANK	New	150.00	0.00
9	TO REMOVE AND REFIT LH FENDER SIDE GLASS	New	120.00	0.00
10	TO SPRAY UNDERSEAL	New	140.00	100.00
11	TO REMOVE AND REFIT SEAT CUSHION	New	200.00	120.00
12	(REAR) TO SPRAY PAINTING	New	1,500.00	1,200.00
13	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS	New	1,600.00	1,300.00
Gross Labour Cost (\$)			4,320.00	3,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >