

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004546/APA3Q2**Date:** 27/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800106987-02
Claimant Vehicle No :	SKP7000P	Insured Vehicle No :	SMD9303S
Date of Loss:	07/05/2022	Nature of Claim:	TP
		Claim No:	7262200324SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP7000P	Engine No:	2AZC610175
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Chassis No:	ACR500092706
Reg. Date:	15/09/2009 (Man. Year: 2009)	Odometer:	251066 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,126.90	4,520.72	1,606.18	26.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	1,670.00	890.00	34.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,686.90	6,190.72	2,496.18	28.73
Approved Total (Overridden) (\$\$)		4,950.00		
(\$\$)	8,686.90	4,950.00	3,736.90	43.02
+ GST 7.00/7.00% (\$\$)	608.08	346.50	261.58	43.02
Nett Amount (\$\$)	9,294.98	5,296.50	3,998.48	43.02
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
Nett Liability (\$\$)		5,896.50		

INSPECTION

Date of Assignment:	11/05/2022	
Date Inspected:	11/05/2022	Inspected At: People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60 Singapore 408717
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN MOULDING REAR	Necessary	118.20 FL	*118.20 FL
2	1		*TAILGATE	Dented	1,819.10 FL	*1,380.00 FL
3	1		*TAILGATE OUTER MOULDING	Cracked	230.10 FL	*230.10 FL
4	1		*TAILGATE LAMP	N/S Cracked	1,160.20 FL	*373.00 FL
5	1		*TAILGATE REFLECTOR	Cracked	189.10 FL	*189.10 FL
6	1		*TAILGATE LOGO	Necessary	65.80 FL	*65.80 FL
7	1		*TAILGATE ESTIMA EMBLEM	Necessary	72.30 FL	*72.30 FL
8	1		*TAILGATE X EMBLEM	Necessary	48.20 FL	*48.20 FL
9	1		*TAILGATE WEATHERSTRIP	Not Necessary	228.30 FL	*- FL
10	1		*TAILGATE INNER LOCK	Damaged	580.10 FL	*371.00 FL
11	1		*TAILGATE INNER BOARD	Cracked	580.10 FL	*580.10 FL
12	1		*BUMPER REAR	Deformed	480.10 FL	*480.10 FL
13	2		*BUMPER BRACKET REAR	Not Necessary	171.20 FL	*- FL
14	2		*BUMPER SIDE RETAINER REAR	Necessary	156.20 FL	*156.20 FL
15	1		*END PANEL REAR	Dented	780.10 FL	*780.10 FL
16	1		*END PANEL TOP GARNISH REAR	Deformed	370.10 FL	*370.10 FL
17	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
18	1		*REVERSE CAMERA	Damaged	450.00 FS	*350.00 FS
19	1		*WINDSCREEN GUM	Necessary	60.00 FS	*60.00 FS
20	1		*NUMBER PLATE AND BASE REAR	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,889.20	5,824.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,762.30	1,303.58
Total Parts (\$\$)	6,126.90	4,520.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	1,200.00	800.00
2	SPRAY PAINTING ACCIDENT AFFECTED PARTS	New	900.00	600.00
3	REMOVE AND REFIX WINDSCREEN REAR	New	120.00	120.00
4	REMOVE AND REFIT REAR UPHOLSTERY CARPET AND ETC	New	160.00	60.00
5	CHECK REAR WIRING AND LIGHTING OPERATION	New	60.00	30.00
6	UNDERCOAT	New	120.00	60.00
Gross Labour Cost (\$\$)			2,560.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >