

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22004551/UPA3Q2**Date:** 02/09/2022REFERENCE

|                              |                                      |                             |               |
|------------------------------|--------------------------------------|-----------------------------|---------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 2100254365-11 |
| <b>Claimant Vehicle No :</b> | SLU8656C                             | <b>Insured Vehicle No :</b> | SKB2266X      |
| Date of Loss:                | 11/05/2022                           | Nature of Claim:            | TP            |
|                              |                                      | Claim No:                   | 2762611654SG  |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SLU8656C</b>                   |             |              |
| Make & Model:               | TOYOTA C-HR HYBRID, 1.8 S CVT (A) | Engine No:  | 2ZR8160532   |
| Reg. Date:                  | 15/12/2017 (Man. Year: 2017)      | Chassis No: | ZYX102061225 |
| Colour:                     | Silver                            | Odometer:   | 112916 km    |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/55Z R18   | Rear Tyre Size:  | 225/55Z R18   |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 27,143.60         | 3,565.12          | 23,578.48         | 86.87         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 5,260.00          | 1,690.00          | 3,570.00          | 67.87         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>32,403.60</b>  | <b>5,255.12</b>   | <b>27,148.48</b>  | <b>83.78</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>4,200.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 32,403.60         | 4,200.00          | 28,203.60         | 87.04         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 2,268.25          | 294.00            | 1,974.25          | 87.04         |
| <b>Nett Amount (S\$)</b>                        | <b>34,671.85</b>  | <b>4,494.00</b>   | <b>30,177.85</b>  | <b>87.04</b>  |
| <b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b> |                   | 500.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>4,996.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>4,990.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                         |
|-----------------------------|------------|---------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 17/05/2022 |                                                                                                         |
| Date Inspected:             | 17/05/2022 | Inspected At: Fastech Auto Pte Ltd (HQ)<br>1 Kaki Bukit Ave 6, #01-46/48/50 Autobay<br>Singapore 417883 |
| Estimated Period of Repair: | 4.0 days   |                                                                                                         |

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition         | Repairer's | Amount       |
|-----|-----|----------|-----------------------------------------|-------------------|------------|--------------|
| 1   | 1   |          | *REAR WINDSCREEN                        | Not Necessary     | 1,488.10 F | *- FL        |
| 2   | 1   |          | *REAR WINDSCREEN MOULDING               | Necessary         | 188.30 F   | *148.50 FL   |
| 3   | 1   |          | *TAILGATE                               | Dented / Bent     | 1,685.10 F | *1,365.10 FL |
| 4   | 1   |          | *TAILGATE REAR LOGO                     | Not Necessary     | 168.50 F   | *- FL        |
| 5   | 1   |          | *TAILGATE OUTER GARNISH                 | Not Necessary     | 344.80 F   | *- FL        |
| 6   | 1   |          | *TAILGATE C-HR EMBLEM                   | Not Necessary     | 96.80 F    | *- FL        |
| 7   | 1   |          | *TAILGATE HYBRID EMBLEM                 | Not Necessary     | 105.00 F   | *- FL        |
| 8   | 2   |          | *TAILGATE REFLECTORS                    | Not Necessary     | 1,300.00 F | *- FL        |
| 9   | 1   |          | *TAILGATE REAR WIPER ARM                | Not Necessary     | 188.90 F   | *- FL        |
| 10  | 1   |          | *TAILGATE REAR WIPER MOTOR              | Not Necessary     | 620.00 F   | *- FL        |
| 11  | 1   |          | *TAILGATE WEATHERSTRIP                  | Not Necessary     | 488.90 F   | *- FL        |
| 12  | 1   |          | *TAILGATE INNER LOCK                    | Bent              | 641.90 F   | *509.20 FL   |
| 13  | 1   |          | *TAILGATE LOCK STRIKER                  | Not Necessary     | 60.00 F    | *- FL        |
| 14  | 1   |          | *TAILGATE INNER TRIM                    | Not Necessary     | 811.60 F   | *- FL        |
| 15  | 2   |          | *TAILGATE INNER LOCK SENSOR             | Not Necessary     | 1,798.00 F | *- FL        |
| 16  | 1   |          | *TAILGATE INNER HOLDER GARNISH          | Not Necessary     | 58.00 F    | *- FL        |
| 17  | 1   |          | *REAR BUMPER                            | Dented / Deformed | 1,215.10 F | *545.10 FL   |
| 18  | 1   |          | *REAR BUMPER CENTRE BLACK GARNISH       | Grazed            | 488.90 F   | *425.10 FL   |
| 19  | 1   |          | *REAR BUMPER BEAM                       | Bent              | 570.20 F   | *399.50 FL   |
| 20  | 2   |          | *REAR BUMPER REFLECTORS                 | Not Necessary     | 170.00 F   | *- FL        |
| 21  | 2   |          | *REAR BUMPER SIDE RETAINERS             | Not Necessary     | 130.00 F   | *- FL        |
| 22  | 1   |          | *REAR BUMPER SPONGE                     | Not fitted        | 199.80 F   | *- FL        |
| 23  | 2   |          | *REAR BUMPER PDC SENSORS                | Shorted           | 570.00 FS  | *200.00 FS   |
| 24  | 1   |          | *REAR END PANEL OUTER                   | Repair            | 899.10 F   | *- FL        |
| 25  | 1   |          | *REAR END PANEL LOCK SENSOR             | Not Necessary     | 350.00 F   | *- FL        |
| 26  | 1   |          | *REAR END PANEL TOP GARNISH             | Not Necessary     | 468.90 F   | *- FL        |
| 27  | 1   |          | *TAILLAMPS                              | N/S Cracked       | 2,101.00 F | *521.80 FL   |
| 28  | 2   |          | *TAILLAMP HOUSING PANELS                | Not Necessary     | 1,300.60 F | *- FL        |
| 29  | 1   |          | *REAR FENDER                            | Not Necessary     | 1,205.10 F | *- FL        |
| 30  | 2   |          | *REAR FENDER INNER TRIM BOARDS          | Not Necessary     | 1,370.20 F | *- FL        |
| 31  | 1   |          | *REAR FENDER OUTER PROTECTOR O/S        | Torn              | 399.20 F   | *399.20 FL   |
| 32  | 1   |          | *REAR FLOOR PANEL                       | Not Necessary     | 1,415.10 F | *- FL        |
| 33  | 1   |          | *REAR FLOOR PANEL TOP BOARD             | Not Necessary     | 622.30 F   | *- FL        |
| 34  | 2   |          | *REAR FLOOR PANEL SIDE TOOL SPONGES     | Not Necessary     | 900.00 F   | *- FL        |
| 35  | 1   |          | *REAR FLOOR PANEL CENTRE TOOLS SPONGE   | Not Necessary     | 520.80 F   | *- FL        |
| 36  | 1   |          | *REAR EXHAUST                           | Repair            | 885.10 F   | *- FL        |
| 37  | 1   |          | *REAR EXHAUST HEAT SHIELD               | Not Necessary     | 188.30 F   | *- FL        |
| 38  | 1   |          | *SET REAR BUMPER CLIPS                  | Necessary         | 50.00 FS   | *50.00 FS    |
| 39  | 1   |          | *REAR WINDSCREEN SEALANT                | Necessary         | 50.00 FS   | *40.00 FS    |
| 40  | 1   |          | *REAR WINDSCREEN INNER SEAL             | Necessary         | 50.00 FS   | *40.00 FS    |
| 41  | 1   |          | *REAR END PANEL SEALANT                 | Not Necessary     | 50.00 FS   | *- FS        |
| 42  | 1   |          | *SET TAILGATE INNER TRIM CLIPS          | Not Necessary     | 50.00 FS   | *- FS        |
| 43  | 1   |          | *SET REAR FLOOR PANEL INSULATOR         | Not Necessary     | 450.00 FS  | *- FS        |
| 44  | 1   |          | *SET REAR FENDER INNER TRIM BOARD CLIPS | Not Necessary     | 50.00 FS   | *- FS        |
| 45  | 1   |          | *SET REAR REVERSE CAMERA                | Not Necessary     | 380.00 FS  | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                         |                  |                 |
|---------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$)</b>                                   | <b>27,143.60</b> | <b>4,643.50</b> |
| <b>- List Item Discount on L Items 0.00/25.00% (\$)</b> | <b>0.00</b>      | <b>1,078.38</b> |
| <b>Total Parts (\$)</b>                                 | <b>27,143.60</b> | <b>3,565.12</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                           |          |                 |                 |
| 1                               | TO CHECK WIRING                           | New      | 50.00           | 20.00           |
| 2                               | TO DISMANTLE & REPLACED REAR PDC SENSOR   | New      | 80.00           | 50.00           |
| 3                               | TO DISMANTLE & REFIX REAR WINDSCREEN      | New      | 150.00          | 120.00          |
| 4                               | TO DISMANTLE & REFIX CUSHION UPHOLSTERY   | New      | 120.00          | 80.00           |
| 5                               | TO RESET & REPROGRAMME DIAGNOSIS SYSTEM   | New      | 100.00          | 50.00           |
| 6                               | TO DISMANTLE & REFIX REAR EXHAUST         | New      | 100.00          | 0.00            |
| 7                               | TO TRANSFER TAILGATE MECHANISM            | New      | 100.00          | 60.00           |
| 8                               | TO SPRAY PROOFING                         | New      | 180.00          | 30.00           |
| 9                               | TO MOUNT VEHICLE ON CAR O-LINER           | New      | 380.00          | 0.00            |
| 10                              | LABOUR FOR PANEL BEATING & REPLACED PARTS | New      | 2,000.00        | 580.00          |
| 11                              | TO PUTTY & SPRAY PAINTING                 | New      | 2,000.00        | 700.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>5,260.00</b> | <b>1,690.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >