

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004552/APA3Q2**Date:** 29/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456266
Claimant Vehicle No :	SLX6307H	Insured Vehicle No :	SLA7700U
Date of Loss:	09/05/2022	Nature of Claim:	TP
		Claim No:	3877049738SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX6307H	Engine No:	G4FGJU164508
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMJU663148
Reg. Date:	03/04/2018 (Man. Year: 2018)	Odometer:	186460 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,892.36	3,442.96	449.40	11.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,010.00	1,500.00	510.00	25.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,902.36	4,942.96	959.40	16.25
Approved Total (Overridden) (S\$)		3,900.00		
Nett Amount (S\$)	5,902.36	3,900.00	2,002.36	33.92
+ Car Rental (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,707.45		
Global Sum Settlement (S\$)		4,700.00		

INSPECTION

Date of Assignment:	10/05/2022	
Date Inspected:	10/05/2022	Inspected At: Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	505.40 FL	*505.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	315.70 FL	*315.70 FL
3	1		*REAR BUMPER LIP	Defaced	255.70 FL	*255.70 FL
4	1		*REAR BUMPER REFLECTOR (L/H)	Cracked	50.40 FL	*50.40 FL
5	1		*REAR BUMPER REFLECTOR (R/H)	Cut	50.40 FL	*50.40 FL
6	10		*BUMPER CLIP	Necessary	60.00 FL	*30.00 FL
7	1		*BUMPER BRACKET (R/H)	Deformed	42.60 FL	*42.60 FL
8	1		*BUMPER BRACKET (L/H)	Deformed	42.60 FL	*42.60 FL
9	1		*BUMPER SIDE RETAINER (L/H/R)	Necessary	32.10 FL	*32.10 FL
10	1		*BUMPER SIDE RETAINER (R/H/R)	Necessary	32.10 FL	*32.10 FL
11	1		*LAMP (REAR R/H /BOOT)	Not Necessary	286.20 FL	*- FL
12	1		*REAR BOOT	Dented	1,883.80 FL	*1,782.00 FL
13	1		*LOGO	Necessary	47.10 FL	*47.10 FL
14	1		*EMBLEM ELANTRA	Necessary	51.20 FL	*51.20 FL
15	1		*REAR BOOT WEATHERSTRIP	Cut	126.80 FL	*126.80 FL
16	1		*REAR BOOT INNER LOCK	Damaged	164.30 FL	*164.30 FL
17	1		*REAR END PANEL	Dented	399.90 FL	*399.90 FL
18	1		*REAR END PANEL GARNISH	Deformed	62.90 FL	*62.90 FL
19	1		*BTL REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
20	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
21	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
					Sub Total (\$\$)	4,774.20 4,241.20
					- List Item Discount on L Items 20.00/20.00% (\$\$)	881.84 798.24
					Total Parts (\$\$)	3,892.36 3,442.96

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE UNDER TURFCOAT	New	150.00	60.00
2	TO CHECK WIRING SYSTEM FOCUS LOGHTING	New	50.00	30.00
3	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	New	60.00	0.00
4	TO REMOVE REVERSE SENSOR	New	80.00	50.00
5	TO TRANSFER REAR BOOT FITTING	New	120.00	60.00
6	PANEL BEATING & REPLACING OF THE ABOVE	New	800.00	700.00
7	TO PUTTY AND RESPRAY AFFECTED PORTION	New	750.00	600.00
Gross Labour Cost (\$\$)			2,010.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >