



**T & C AUTOMOBILE ASSESSORS****ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS**

Vechile No : SLH7253G

Report No : TC/2019/469

<u>S/NO</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION/ REMARKS</u>	<u>REPAIRER'S ESTIMATES</u> S\$	<u>OUR ASSESSMENT</u> S\$
1	1	Front bumper	Deformed	1,398.70	1,398.70
2	1	Front bumper lower lid	Deformed	641.20	641.20
3	1	Front bumper lower splash guard	Deformed	582.70	582.70
4	1	Front LH bumper side retainer	Broken	96.30	96.30
5	1	Front bumper reinforcement	Bent	949.80	949.80
6	1	Front LH bumper sponge	Broken	82.40	82.40
7	1	Front LH bumper bracket	Bent	163.90	163.90
8	1	Front bumper top bracket	Bent	571.60	571.60
9	1 set	Front bumper clips	Necessary	60.00	60.00
10	1	Front grille assy	Broken	982.10	982.10
11	1	Front grille top rubber moulding	Torn	118.70	118.70
12	1	Front bonnet	Buckled	1,497.20	1,497.20
13	1	Front LH fender	Dented	744.90	744.90
14	1	Front LH fender inner shield	Deformed	283.40	283.40
15	1 set	Front fender inner shield clips	Necessary	50.00	50.00
16	1	Front LH foglamp	Broken/cracked	566.70	566.70
17	1	Front LH foglamp cover	Necessary	191.50	191.50
18	1	Front LH headlamp	Broken/cracked	2,756.30	2,756.30
19	1	Front LH headlamp bracket	Bent	43.80	43.80
20	1	Front LH headlamp panel	Bent	272.50	272.50
21	1	Front RH headlamp	Broken/cracked	2,756.30	2,756.30
22	1	Front support LH side panel	Bent	647.20	647.20
23	1	Front LH lower arm	Bent	682.30	682.30
24	1	Front LH knuckle arm	Bent	733.10	733.10
25	1	Front LH wheel hub & bearing	Deformed	457.30	457.30
26	2	Front shock absorber	Bent	759.40	759.40
27	1	Drive shaft	Broken	1,143.10	1,143.10
				19,232.40	19,232.40
Less : Discount 10%				-1,923.24	-1,923.24
<b>Total :</b>				<b>17,309.16</b>	<b>17,309.16</b>
<b><u>SPECIAL NETT ITEMS</u></b>					
28	1	18" sport rim	Dented	780.00	780.00
29	1	Tyre	Torn	650.00	650.00
30	1	Front number plate and casing	Dented	80.00	80.00
				1,510.00	1,510.00
<b>Total Spare Parts :</b>				<b>18,819.16</b>	<b>18,819.16</b>

**T & C AUTOMOBILE ASSESSORS****LABOUR CHARGES**

Vehicle No : SLH7253G

Report No : TC/2019/469

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
1	To tow vehicle from Kluang to Singapore workshop.	1,200.00	1,200.00
2	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	2,200.00	1,900.00
3	To putty and respray painting on affected areas.	2,000.00	1,700.00
4	To rewire and check lightings for front portion.	150.00	100.00
5	To remove, refix front undercarriage.	750.00	650.00
6	To conduct computerised wheel alignment test.	150.00	120.00
7	To apply undersealing.	300.00	250.00
<b>Total Labour Charges :</b>		<b>6,750.00</b>	<b>5,920.00</b>
<b>Total Spare Parts :</b>		<b>18,819.16</b>	<b>18,819.16</b>
<b>Total Repair Costs :</b>		<b>25,569.16</b>	<b>24,739.16</b>

**Assessor's Recommendation****Repairer Estimate :** 25,569.16**Our Adjustment :** 24,739.16**Remarks**The repairer has agreed to undertake the repair of **S\$24,739.16**, with a repair period of 13 working days.

Surveyed By:

THAM KOK SANG