



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 770Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER TOP	GRAZED	1,567.00	1,567.00
1	REAR BUMPER BOTTOM	GRAZED	985.00	985.00
1	REAR BUMPER REFLECTOR O/S	GRAZED	132.00	132.00
1	REAR BUMPER SIDE LH	DEFORMED	299.00	299.00
1	REAR BUMPER TOP RETAINER	CRACKED	312.00	312.00
1	REAR BUMPER SIDE RETAINER N/S	CRACKED	145.00	145.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER PDC SENSOR O/S	SERVICEABLE	182.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	915.00	-
1	TAILLAMP N/S	CRACKED	815.00	815.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	2,420.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	900.00	-
	LESS 10% DISCOUNT		-872.20	-430.50
			7,849.80	3,874.50
LABOUR				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO RESET & DIAGNOSTIC SYSTEM.		180.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR END PANEL.		800.00	500.00
	TO PUTTY & SPRAY PAINTING.		980.00	600.00
			2,260.00	1,330.00
GRAND TOTAL			10,109.80	5,204.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,150.00

Report Ref No. CS/TP22004555/Uvce2


CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.