

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 770Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER TOP	GRAZED	1,567.00	1,567.00
1	REAR BUMPER BOTTOM	GRAZED	985.00	985.00
1	REAR BUMPER REFLECTOR O/S	GRAZED	132.00	132.00
1	REAR BUMPER SIDE LH	DEFORMED	299.00	299.00
1	REAR BUMPER TOP RETAINER	CRACKED	312.00	312.00
1	REAR BUMPER SIDE RETAINER N/S	CRACKED	145.00	145.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER PDC SENSOR O/S	SERVICEABLE	182.00	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	915.00	-
1	TAILLAMP N/S	CRACKED	815.00	815.00
1	REAR FENDER N/S	TO REPAIR SEE LABOUR	2,420.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	900.00	-
	LESS 10% DISCOUNT		-872.20	-430.50
			7,849.80	3,874.50
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REFIX REAR PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO RESET & DIAGNOSTIC SYSTEM.		180.00	80.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER N/S AND REAR END PANEL.		800.00	500.00
	TO PUTTY & SPRAY PAINTING.		980.00	600.00
			2,260.00	1,330.00
	GRAND TOTAL		10,109.80	5,204.50



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP22004555/Uvce2

CHUA KANG SENG
Licensed Appraiser