

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22004562/AYA3Q2**Date:** 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480186
<b>Claimant Vehicle No :</b>	GBE6500J	<b>Insured Vehicle No :</b>	SLF7805A
Date of Loss:	11/05/2022	Nature of Claim:	TP
		Claim No:	0902843211SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBE6500J</b>	Engine No:	1KD2584479
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y10K205950
Reg. Date:	24/02/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	155 R13C
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	28,296.65	10,702.07	17,594.58	62.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,110.00	4,920.00	5,190.00	51.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>38,406.65</b>	<b>15,622.07</b>	<b>22,784.58</b>	<b>59.32</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>12,500.00</b>		
	<b>(S\$)</b>	38,406.65	12,500.00	25,906.65
<b>+ GST 7.00/7.00% (S\$)</b>	2,688.47	875.00	1,813.47	67.45
<b>Nett Amount (S\$)</b>	<b>41,095.12</b>	<b>13,375.00</b>	<b>27,720.12</b>	<b>67.45</b>
<b>+ Car Rental (20.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		2,140.00		
	<b>(S\$)</b>	15,515.00		
<b>Liable Amount (50.00%) (S\$)</b>		<b>7,757.50</b>		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>+ Other Costs (S\$)</b>		120.00		
<b>Nett Liability (S\$)</b>		<b>7,879.50</b>		

**INSPECTION**

Date of Assignment:	13/05/2022		
Date Inspected:	13/05/2022	Inspected At:	SM Automotive (HQ) BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883
Estimated Period of Repair:	14.0 days		

---

**Adjuster:** ADRIAN LING

**Manager:** Ezlyna

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH FRONT UPPER ARM	Bent	316.80 FL	*316.80 FL
2	1		*LH FRONT LOWER ARM	Bent	670.10 FL	*670.10 FL
3	1		*LH FRONT KNUCKLER ARM	Damaged	570.90 FL	*570.90 FL
4	1		*LH FRONT KNUCKLER ARM BEARING WITH HUB	Damaged	221.40 FL	*221.40 FL
5	1		*LH FRONT SHOCK ABSORBER	Bent	351.20 FL	*351.20 FL
6	1		*LH FRONT BRAKE CALIPER PUMP	Not Necessary	361.40 FL	*- FL
7	1		*LH FRONT BRAKE ROTOR DISC	Not Necessary	178.20 FL	*- FL
8	1		*LH FRONT STEP PANEL	Not Necessary	398.10 FL	*- FL
9	1		*LH FRONT STEP PANEL GARNISH	Not Necessary	212.40 FL	*- FL
10	1		*FRONT ANTI ROLL BAR	Bent	789.10 FL	*789.10 FL
11	2		*FRONT ANTI ROLL BAR BUSH	Damaged	343.80 FL	*150.00 FL
12	1		*FRONT CROSSMEMBER	Bent	1,290.00 FL	*1,290.00 FL
13	1		*FRONT STEERING RACK & PINION	Damaged	1,718.10 FL	*1,718.10 FL
14	1		*LH FRONT LOWER ARM BALL JOINT	Damaged	278.10 FL	*278.10 FL
15	1		*POWER STEERING RESERVOIR TANK	Not Necessary	470.10 FL	*- FL
16	1		*POWER STEERING RESERVOIR TANK BRACKET	Not Necessary	78.90 FL	*- FL
17	2		*POWER STEERING RESERVOIR HOSE	Not Necessary	93.60 FL	*- FL
18	1		*BATTERY TRAY	Distorted	330.20 FL	*125.00 FL
19	1		*BATTERY BRACKET	Distorted	270.10 FL	*270.10 FL
20	1		*BATTERY TERMINAL WIRE HARNESS (POSITIVE)	Smashed	1,894.60 FL	*455.00 FL
21	1		*DIESEL FUEL PUMP	Cracked	368.10 FL	*368.10 FL
22	1		*DIESEL FUEL FILTER	Damaged	230.90 FL	*230.90 FL
23	1		*DIESEL FUEL PUMP SWITCH	Damaged	178.40 FL	*178.40 FL
24	2		*DIESEL FUEL PUMP RUBBER HOSE	Not Necessary	260.40 FL	*- FL
25	1		*LH FRONT FUSE BOX / WIRE HARNESS	Cracked	1,764.80 FL	*844.00 FL
26	1		*LH FRONT INNER REAR COWLING	Deformed	370.10 FL	*370.10 FL
27	1		*LH FRONT INNER CENTER COWLING	Deformed	313.20 FL	*313.20 FL
28	1		*LH FRONT INNER COWLING BRACKET	Bent	228.10 FL	*228.10 FL
29	1		*LH REAR MUDGUARD	Dented	374.90 FL	*374.90 FL
30	1		*LH REAR MUDGUARD BRACKET	Not Necessary	189.40 FL	*- FL
31	1		*AIR CON CONDENSER	Not Necessary	1,025.30 FL	*- FL
32	1		*AIR CON CONDENSER BRACKET	Not Necessary	113.40 FL	*- FL
33	1		*AIR CON CONDENSER RUBBER MAT	Not Necessary	42.60 FL	*- FL
34	1		*AIR CON CONDENSER FAN / MOTOR WITH COWLING	Not Necessary	985.60 FL	*- FL
35	1		*FRONT CABIN STAND	Bent	237.60 FL	*237.60 FL
36	1		*FRONT CABIN ENGINE REAR GUARD BAR	Not Necessary	1,478.60 FL	*- FL
37	1		*FRONT CABIN ENGINE REAR GUARD BAR LOWER BRACKET	Not Necessary	653.10 FL	*- FL
38	1		*LH INTER COOLER	Not Necessary	435.60 FL	*- FL
39	1		*LH INTER COOLER INLET HOSE	Not Necessary	65.40 FL	*- FL
40	1		*LH INTER COOLER OUTLET HOSE	Not Necessary	75.40 FL	*- FL
41	1		*LH INTER COOLER RETURN HOSE	Not Necessary	23.10 FL	*- FL
42	1		*LH GLOW PLUG CONTROLLER	Not Necessary	386.10 FL	*- FL
43	1		*LH SIDE GATE	Dented	1,865.00 FL	*1,865.00 FL
44	1		*BATTERY	Smashed	220.00 FS	*220.00 FS
45	1		*LH FRONT RIM	Bent	550.00 FS	*250.00 FS
46	1		*LH FRONT TYRE	Cut	280.00 FS	*200.00 FS
47	1		*REAR CARGO PLATFORM	Repair	6,500.00 FS	*- FS
48	1		*REAR CARGO PLATFORM CHECKER PLATE	Not Necessary	1,800.00 FS	*- FS
49	1		*BATTERY TERMINAL WIRE (NEGATIVE)	Distorted	180.00 FS	*180.00 FS
50	2		*BATTERY TERMINAL WIRE CLAMP	Damaged	50.00 FS	*50.00 FS
51	1		*REAR CARGO SIDE GATE COMPANY STICKER	Necessary	1,200.00 FS	*400.00 FS
52	2		*LH FRONT INNER COWLING CLIPS	Not Necessary	60.00 FS	*- FS
53	8		*REAR CARGO RUBBER MOUNTING	Necessary	360.00 FS	*200.00 FS
54	1		*SET FRONT BRAKE PAD	Not Necessary	160.00 FS	*- FS
55	1		*POWER STEERING OIL	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Sub Total (\$)</b>	<b>33,922.20</b>	<b>13,756.10</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	5,625.55	3,054.03
					<b>Total Parts (\$)</b>	<b>28,296.65</b>	<b>10,702.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR PANEL BEATING	New	1,800.00	800.00
2	LABOUR FOR SPRAYPAINTING	New	1,600.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	TO APPLY TUFF COATING / RUST PROOF ACCIDENT AREAS	New	400.00	100.00
5	LABOUR FOR REMOVE & NEW BATTERY / TRAY / BRACKET / WIRING	New	300.00	180.00
6	LABOUR FOR REMOVE & RENEW LH FRONT FUSE BOX	New	200.00	200.00
7	LABOUR FOR REMOVE & RENEW FRONT UNDER CARRIAGE	New	500.00	350.00
8	LABOUR FOR CLEAR & BLEEDE FUEL SYSTEM	New	180.00	100.00
9	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
10	TO WASH & CLEAR UP LH BATTERY ACID	New	300.00	50.00
11	LABOUR FOR REMOVE & RENEW REAR CARGO PLATFORM	New	800.00	500.00
12	LABOUR FOR REPAIR & STRAIGHTEN BOTH CHASSIS FRAME	New	800.00	200.00
13	LABOUR FOR REMOVE & RENEW ALL BRAKE & STEERING SYSTEM	New	500.00	150.00
14	LABOUR FOR REMOVE & BLEEDE BRAKE SYSTEM	New	150.00	80.00
15	LABOUR FOR REMOVE & REFIX FRONT CABIN TO FACILITATE THE REPAIR	New	800.00	500.00
16	LABOUR FOR REMOVE & TRANSFER BOTH REAR SIDE GATE RAILING	New	400.00	0.00
17	LABOUR FOR REMOVE & RENEW AIR CON CONDENSER, TOP UP AIR CON GAS	New	150.00	0.00
18	LABOUR TO REPAIR AND STRAIGHTEN CHASSIS MEMBER	New	1,000.00	800.00
			<b>Gross Labour Cost (S\$)</b>	<b>10,110.00</b>
				<b>4,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >