

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004565/APA3Q2**Date:** 31/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800025024
Claimant Vehicle No :	SND5197X	Insured Vehicle No :	SLX7178G
Date of Loss:	12/05/2022	Nature of Claim:	TP
		Claim No:	0495796517SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SND5197X		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZR575497
Reg. Date:	28/06/2016 (Man. Year: 2016)	Chassis No:	MR053REH104551446
Colour:	White	Odometer:	169057 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,811.10	2,926.50	4,884.60	62.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	840.00	1,510.00	64.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,161.10	3,766.50	6,394.60	62.93
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	10,161.10	3,000.00	7,161.10	70.48
+ GST 8.00/8.00% (\$\$)	812.89	240.00	572.89	70.48
Nett Amount (\$\$)	10,973.99	3,240.00	7,733.99	70.48
+ Loss of Use (6.0 x S\$60.00/day) (\$\$)		360.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		3,607.45		
Global Sum Settlement (\$\$)		3,600.00		

INSPECTION

Date of Assignment:	13/05/2022	Green Forest Automobile Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4, #05-25,, Premier@Kaki Bukit Singapore 415875
Date Inspected:	13/05/2022 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP TOP CHROME - RH	Not Necessary	188.00 F	*- FL
2	1		*FRONT HEADLAMP - RH	Cut	1,380.00 F	*1,380.00 FL
3	1		*FRONT GRILLE	Not Necessary	315.00 F	*- FL
4	1		*GRILLE CLIPS	Not Necessary	50.00 F	*- FL
5	1		*FRONT GRILLE EMBLE LOGO	Not Necessary	65.00 F	*- FL
6	1		*FRONT BUMPER	Deformed	820.00 F	*581.00 FL
7	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	246.40 F	*- FL
8	8		*FRONT BUMPER CLIPS	Necessary	103.20 F	*30.00 FL
9	1		*FRONT BUMPER NUMBER PLATE	Not Necessary	50.00 F	*- FL
10	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	270.00 F	*- FL
11	1		*FRONT BUMPER SIDE RETAINER	O/S Damaged	330.40 F	*65.00 FL
12	1		*FRONT BUMPER FOG LAMP COVER - RH	Not Necessary	155.00 F	*- FL
13	1		*FRONT FOG LAMP - RH	Cracked	254.00 F	*254.00 FL
14	1		*WATER TANK	Deformed	285.00 F	*110.00 FL
15	1		*FRONT FENDER - RH	Not Necessary	855.00 F	*- FL
16	1		*FRONT FENDER MUD SHIELD - RH	Not Necessary	153.90 F	*- FL
17	1		*FRONT FENDER INNER COWLING - RH	Torn	184.00 F	*184.00 FL
18	8		*FRONT FENDER COWLING CLIPS	Necessary	103.20 F	*30.00 FL
19	1		*FRONT TYRE - RH	Not Necessary	350.00 F	*- FL
20	1		*FRONT SPORT RIM - RH	Cut	500.00 F	*500.00 FL
21	1		*FRONT SHOCK ABSORBER - RH	Not Necessary	385.00 F	*- FL
22	1		*FRONT KNUCKLE ARM - RH	Damaged	285.00 F	*285.00 FL
23	1		*FRONT LOWER ARM - RH	Bent	295.00 F	*295.00 FL
24	1		*FRONT WHEEL BEARING - RH	Damaged	188.00 F	*188.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,811.10	3,902.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	975.50
Total Parts (S\$)	7,811.10	2,926.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT CUSHION	New	120.00	0.00
2	TO REMOVE & REFIT FRONT UNDERCARRIAGE	New	280.00	200.00
3	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	80.00
4	TO CHECK WIRING	New	80.00	30.00
5	TUFF KOTE	New	120.00	30.00
6	PANEL BEATING	New	800.00	300.00
7	SPRAY PAINTING	New	800.00	200.00
Gross Labour Cost (S\$)			2,350.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >