

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22004572/APA3Q2**Date:** 30/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000003471
Claimant Vehicle No :	SKV717U	Insured Vehicle No :	SMR5721X
Date of Loss:	16/05/2022	Nature of Claim:	TP
		Claim No:	6820713239SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV717U	Engine No:	4B12PT8107
Make & Model:	MITSUBISHI OUTLANDER, 2.4 CVT (A)	Chassis No:	JMYXTGF3WGW000761
Reg. Date:	21/08/2015 (Man. Year: 2015)	Odometer:	196470 km
Colour:	White		
Engine Capacity:	2360 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,313.00	8,184.10	6,128.90	42.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	2,570.00	1,870.00	42.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,753.00	10,754.10	7,998.90	42.65
Approved Total (Overridden) (S\$)		8,600.00		
Nett Amount (S\$)	18,753.00	8,600.00	10,153.00	54.14
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Other Costs (S\$)		160.00		
Nett Liability (S\$)		9,560.00		
Global Sum Settlement (S\$)		9,500.00		

INSPECTION

Date of Assignment:	17/05/2022	
Date Inspected:	17/05/2022	Inspected At: ADVANCE AUTO GARAGE (23 KAKI BUKIT) (HQ) 25 KAKI BUKIT AVE 4 #04-01 VICOM KAKI BUKIT Singapore 415933
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	807.00 F	*807.00 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER RH	Damaged	28.00 F	*28.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Not Necessary	232.00 F	*- FL
5	1		*REAR RH FENDER	Distorted	1,114.00 F	*1,114.00 FL
6	1		*REAR RH FENDER INNER TRIM BOARD	Not Necessary	796.00 F	*- FL
7	1		*REAR RH FENDER INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
8	1		*REAR RH FENDER INNER SHIELD	Torn	89.00 F	*89.00 FL
9	1		*REAR RH FENDER INNER SHIELD CLIPS	Necessary	20.00 FS	*20.00 FS
10	1		*REAR RH FENDER ARC GARNISH	Cut	179.00 F	*179.00 FL
11	1		*REAR RH FENDER GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
12	1		*REAR RH DOOR	Dented	1,088.00 F	*1,088.00 FL
13	1		*REAR RH DOOR LOCK	Damaged	348.00 F	*348.00 FL
14	1		*REAR RH DOOR WEATHERSTRIPE	Cut	168.00 F	*168.00 FL
15	1		*REAR RH DOOR INNER TRIM BOARD	Cracked	598.00 F	*598.00 FL
16	1		*REAR RH DOOR INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
17	1		*REAR RH DOOR BLACK TAPE	Necessary	50.00 FS	*50.00 FS
18	1		*REAR RH DOOR GLASS REGULATOR GEAR	Not Necessary	258.00 F	*- FL
19	1		*REAR RH DOOR PROTECTOR	Cut	205.00 F	*205.00 FL
20	1		*REAR RH DOOR PROTECTOR CLIPS	Necessary	20.00 FS	*20.00 FS
21	1		*ROCKER PANEL RH	Repair	867.00 F	*- FL
22	1		*ROCKER PANEL OUTER GARNISH	Deformed	695.00 F	*695.00 FL
23	1		*ROCKER PANEL OUTER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
24	1		*TAILLAMP RH	Not Necessary	506.00 F	*- FL
25	1		*REAR RH WHEEL RIM	Cut	1,650.00 FS	*700.00 FS
26	1		*REAR RH TYRE	Not Necessary	350.00 FS	*- FS
27	1		*REAR RH LOWER ARM	Bent	298.00 F	*298.00 FL
28	1		*REAR RH CONTROL ARM	Bent	198.00 F	*198.00 FL
29	1		*REAR RH UPPER ARM	Bent	228.00 F	*228.00 FL
30	1		*REAR RH KNUCKLE ARM	Damaged	610.00 F	*610.00 FL
31	1		*REAR RH WHEEL HUB C/W BEARING	Damaged	245.00 F	*245.00 FL
32	1		*REAR RH SHOCK ABSORBER	Damaged	425.00 F	*425.00 FL
33	1		*REAR CROSS MEMBER	Not Necessary	1,290.00 F	*- FL
34	1		*REAR EXHAUST PIPE	Dented	688.00 F	*688.00 FL
35	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.00 F	*- FL
36	1		*REAR EXHAUST PIPE GASKET	Necessary	38.00 F	*38.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,313.00	8,989.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	804.90
Total Parts (\$)	14,313.00	8,184.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	900.00
2	SPRAY PAINTING	New	1,400.00	900.00
3	WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	150.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	60.00
6	TO TRANSFER REAR DOOR FITTINGS	New	150.00	80.00
7	TO REMOVE REAR FENDER GLASS	New	120.00	40.00
8	TO REMOVE REAR EXHAUST PIPE	New	150.00	80.00
9	TO REMOVE REAR UNDERCARRIAGE	New	350.00	220.00
10	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
11	TOWING CHARGES (KING ROLLER)	New	120.00	120.00
Gross Labour Cost (\$)			4,440.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >