

Bussiness Regn No: 201416413W

ACCIDENT VEHICLE INSPECTION / ASSESSMENT REPORT

REFERENCE

Our reference no

: TP/FBP3800E/EB/1019/08

Date of request

: 30-Oct-2019

Date of survey

: 30-Oct-2019

Date of accident

: 19-Oct-2019

Requested by

: GOH JIA WEI, JEREMY

C/o , Blk 25 Kaki Bukit Rd 4 Synergy@KB, #03-79.Singapore 417800

Type of claim

: Third party

Workshop

: EQUATOR BROTHERHOOD

Blk 25, Kaki Bukit Rd 4 Synergy@KB, #03-79

Singapore 417800

DETAILS OF VEHICLE

Registration No.

: FBP3800E

Make & Model

: HONDA CB400 SF4J M

Date of registration

: 14/3/2005 (COE Expiry 28/2/2025)

Engine No.

: NC23E2066684

Engine Capacity

: 399CC

Chassis No.

: NC391056516

Speedometer reading

: 11,103KM

Colour

: BLUE

3 STATIC CHECK

Steering

: Bent

Paintwork

: Good

Footbrake

: In order

Modification

: Nil

Handbrake

: In order

General condition : Good

TYRE CONDITION

Nearside/Make

Size

Front tyre

: 3mm/Pirelli

120/60R17

Rear tyre

: 3mm/Pirelli

160/60R17

5 POINT OF IMPACT

The said vehicle has sustained an impact damages on the rear and right portion. Kindly refer to the attached photographs for more detail of the damages.

6 REMARK

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not authorised any repair.

Annex A: Assessement / Adjustment on Spare Parts TP/FBP3800E/EB/1019/08

tem	Vehicle Parts Description	Conditio	n Qty	W/shop Est. (\$)	Disc (%)	Adjusted Cost (\$)
	List Items	AND ADDRESS OF THE PARTY OF THE		2011(4)	(70)	COSE (\$)
1	Honda rear swingarm He	distorted	1	00 000	100/	¢700.00
2	Honda rear swingarm bush	necessary	1	\$880.00 \$180.00	10%	\$792.00
3	Honda rear swingarm shaft * Ke ~	distorted	1	\$120.00	10%	\$162.00
1	Honda rear suspension NM MW	distorted	2		10%	\$108.00
5	Honda rear number plate holder	distorted	4	\$1,300.00	10%	\$1,170.00
5	Honda rear number plate reflector	intact	1	\$95.00	10%	\$85.50
7	Honda rear rim 7		1	\$25.00	100%	\$0.00
	Honda rear wheel bearing	warped/wobble	1	\$680.00	10%	\$612.00
)	Honda rear wheel seal	rattle	2	\$70.00	10%	\$63.00 {
	Honda rear wheel shaft	necessary	2	\$30.00	10%	\$27.00
	Honda chain guard	serviceable	1	\$110.00	100%	\$0.00
2	Honda rear tail board	intact	1	\$65.00	100%	\$0.00 8
		repair/spray	24210	\$380.00	100%	\$0.00
	Honda exhaust manifold MR MeV	distorted	24/34	\$680.00	10%	\$612.00×
			-	\$4,615.00	-	\$3,631.50
	S/Nett Items	M-				
	p. o.cocoi	grazed	1	\$120.00		\$120.00
	GPR rear signal light set	broken	1	\$65.00		\$65.00
	Yoshimura exhaust	dented badly	1	\$1,200.00		\$1,200.00
		•		Ψ1,200.00		\$1,200.00
				\$1,385.00	-	\$1,385.00
	Total for Spa		pare Parts :	\$6,000.00		\$5,016.50
						865

Annex B: Adjustment on Labour and Spray Painting TP/FBP3800E/EB/1019/08

Item	Job Description	Workshop Est. (\$)	Adjusted Cost (\$)
1	To remove & replace rear rim, swing arm, bush, rear suspension.	\$250.00	\$180.00 120
2	To remove & replace above body damaged parts,check wiring & lighting system	\$450.00	\$380.60200
3	To respray paint right rear fairing.	\$200.00	\$120.00
4	To conduct rear chassis alignment	\$350.00	\$280.00 🔀
5	Towing -workshop to accident reporting center 420	\$50.00	\$50.00
6	Towing -accident reporting center to workshop	\$50.00	\$50.00
	-	\$1,350.00	\$1,060.00
	TOTAL FOR LABOUR & SPRAY PAINTING :	\$1,350.00	\$1,060.00

Summary

	Workshop Est. (\$)	Adjusted Cost (\$)	
TOTAL FOR SPARE PARTS : TOTAL FOR LABOUR & SPRAY PAINTING :	401000100	\$5,016.50 \$1,060.00	
TOTAL REPAIR COSTS :	\$7,350.00	\$6,076.50	

TP/FBP3800E/EB/1019/08

Annex C: Recommendation

We have inspected thoroughly the actual damages found on the vehicle and our assessment is appended in the Annex(es) attached. The condition and age of the vehicle was considered before we reached our recommendation as to whether the parts need replacement or repair.

M/S Equator Brotherhood estimated repair cost is \$\$7,350.00 and we have adjusted it to S\$6,076.50 on a part by part basis. However, taking into consideration the age of the vehicle and the availability of used/recondition components. We, therefore recommend a contract lump sum repair cost.

The repairer have agreed to undertake the repairs on a contract lump sum of \$\$4,800.00, according to acceptable quality and standard. (Repairer discretion to repair parts, to replace with old parts, or to replace with OEM or genuine parts).

The entire repair of the damaged vehicle should be completed within a reasonable period of 4 working days.

We have advised the repairer that the inspection was conducted strictly on a WITHOUT PREJUDICE basis and we have not given any instruction and authorisation to proceed with the repair of the vehicle.

We are reverting the matter to you for your discretion and enclosed is our invoice for service rendered.

Yours faithfully.

Henry Low

Automotive License Appraiser

CMTM, DMTM, IPTM (UNF)

total: 1532.5 HS1 1.21C.



Insurance Loss Adjusters and Motor Appraisers Blk 779 #01-1545 Yishun Ave 2 Singapore 760779 Tel: 62934822 Fax: 62963283 E-mail: admin@priorityservices.sg

Date:

15 September 2020

Your Ref:

CMTD1904973

Our Ref:

TP-0057/09/20

Vocon.

Motor Claims Department M/s. Sompo Insurance Pte. Ltd. 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623

Attention: Ms. Agnes Chan

Madam,

Inspection of 2005 Honda CB400 Motorcycle

Registration No.: FBP 3800 E

Odometer Reading: 11103 km (At the time of Pre-repair Inspection)

Chassis No.: NC391056516

We refer to your instructions to us to conduct a paper survey of the above vehicle. A prerepair survey was conducted on 30-10-2019, followed by inspection of dismantled parts on 01-11-2019 and resurvey after repairs on 05-11-2019.

The following documents were received: -

- 1) Copy of survey report by M/s. Advanced Automotive Consultancy Pte Ltd
- 2) 26 copies of photos depicting damages sustained by FBP 3800 E and 10 copies of after repair photos
- 3) Accident and police reports by riders of FBP 3800 E and FBN 1822 R
- 4) 20 copies of scene photos and 6 copies of photos showing condition of FBN 1822 R

The vehicle sustained rear damages during an accident on 19-10-2019.

Repair cost submitted was \$4,800.00 lump-sum.

We append below our findings: -

Replacement of Parts		Revised Amount		Our Recommendation	
lpc.	Honda rear swing arm – not affected/refitted	\$	792.00	\$	-
lpc.	Honda rear swing arm bush – not necessary		162.00		-
lpc.	Honda rear swing arm shaft – not affected/refitted		108.00		-

2pcs.	Honda rear suspension – not affected Honda rear number plate holder – dented/cut	\$	1,170.00 85.50	\$	85.50
lpc. 2pcs.	Honda rear rim – not affected/refitted Honda rear wheel bearing – not affected		612.00 63.00		.# -
2pcs.	Honda rear wheel seal – not necessary Honda exhaust manifold – not affected		27.00 612.00		-
		\$	3,631.50	\$	85.50
Special	Nett Items:-		*		
lpc.	R&G exhaust protector – no such item during our pre-repair inspection	\$	120.00	\$	
lpc.	GPR rear signal light set – broken Yoshimura exhaust – dented (price checked)		65.00 1,200.00		65.00 700.00
	Total For Parts:-	\$	5,016.50	\$	850.50
Labour Charges:-					
	ove and replace rear rim, swing arm, ar suspension.	\$	180.00	\$	-
To remove and replace above body damaged parts, check wiring and lighting system.			380.00		180.00
To respi	ray paint right rear fairing.		120.00		· .
To cond	luct rear chassis alignment.		280.00		-
Towing – not ne	- workshop to accident reporting center cessary		50.00		ü
Towing – not ne	accident reporting center to workshop cessary		50.00		-
	Total :-	\$	6,076.50	\$	1,030.50
Lump-sı	ım repairs:	\$	4,800.00	\$	800.00

Estimated period of repairs: 2 working days

Pre-accident Market Value: About \$8,000.00 (At the time of accident)
COE rebate: \$2,394.00 (COE expiry on 28-02-2025)

Vehicle within economical limit to repair.

Economical limit to repair : About \$5,600.00

We leave the decision of settlement to you.

Assuring you of our best services always

Yours faithfully

PRIORITY SERVICES

JIMMY S. T. LEE AMSOE, AMIRTE, MSAAA Motor Appraiser

Surveyed by:

LAWRENCE NG, MSAAA Motor Appraiser