



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3800E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HONDA REAR SWINGARM	NOT NECESSARY	880.00	-
1	HONDA REAR SWINGARM BUSH	NECESSARY	180.00	180.00
1	HONDA REAR SWINGARM SHAFT	NOT NECESSARY	120.00	-
2	HONDA REAR SUSPENSION	NOT NECESSARY	1,300.00	-
1	HONDA REAR NUMBER PLATE HOLDER	DISTORTED	95.00	95.00
1	HONDA REAR NUMBER PLATE REFLECTOR	INTACT	25.00	-
1	HONDA REAR RIM	NOT NECESSARY	680.00	-
2	HONDA REAR WHEEL BEARING	NOT NECESSARY	70.00	-
2	HONDA REAR WHEEL SEAL	NOT NECESSARY	30.00	-
1	HONDA REAR WHEEL SHAFT	SERVICEABLE	110.00	-
1	HONDA CHAIN GUARD	INTACT	65.00	-
1	HONDA REAR TAIL BOARD	TO REPAIR SEE LABOUR	380.00	-
1	HONDA EXHAUST MANIFOLD	NOT NECESSARY	680.00	-
	LESS 10% DISCOUNT		-	-27.50
			4,615.00	247.50
<u>SPECIAL NETT ITEMS</u>				
1	R&G EXHAUST PROTECTOR (SN)	NO SUCH PARTS	120.00	-
1	SET GPR REAR SIGNAL LIGHT (SN)	BROKEN	65.00	65.00
1	YOSHIMURA EXHAUST (SN)	DENTED BADLY	1,200.00	800.00
			1,385.00	865.00
<u>LABOUR</u>				
	TO REMOVE & REPLACE REAR RIM, SWING ARM, BUSH, REAR SUSPENSION.		250.00	120.00
	TO REMOVE & REPLACE ABOVE BODY DAMAGED PARTS, CHECK WIRING & LIGHTING SYSTEM. INCLUSIVE OF THE REPAIR OF HONDA REAR TAIL BOARD.		450.00	200.00
	TO RESPRAY PAINT RIGHT REAR FAIRING.	NOT NECESSARY	200.00	-
	TO CONDUCT REAR CHASSIS ALIGNMENT.	NOT NECESSARY	350.00	-
	TOWING-WORKSHOP TO ACCIDENT REPORTING CENTER.		50.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING-ACCIDENT REPORTING CENTER TO WORKSHOP.		50.00	50.00
			1,350.00	420.00
GRAND TOTAL			7,350.00	1,532.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS1/LAW22004577/Avce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.