



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 3123D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,219.00	671.00
1	FRONT LH RETAINER	CRACKED	187.00	187.00
1	FRONT LH HEADLAMP	SCRATCHED	1,523.00	1,246.00
	LESS 25% DISCOUNT		-732.25	-526.00
			2,196.75	1,578.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET FRONT HEADLAMP CLIP (SN)	NECESSARY	107.00	30.00
			187.00	60.00
	<u>LABOUR</u>			
	SPRAY PAINTING ON AFFECTED AREAS.		800.00	200.00
	LABOUR TO REMOVE AND INSTALL AFFECTED PARTS.		800.00	200.00
			1,600.00	400.00
	GRAND TOTAL		3,983.75	2,038.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,650.00

Report Ref No. CS/SMR22004581/Vcy3m4

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.