#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22004587/VQY3E2

14/07/2022 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001959529

**Claimant Vehicle** FBT571P Insured Vehicle No: SLG4299A No:

Date of Loss: 13/05/2022 Nature of Claim: TP Claim No: 274461

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBT571P

Make & Model: YAMAHA NMAX155, 155cc ABS CVT G3L8E0689347 Engine No:

Reg. Date: 25/10/2021 (Man. Year: 2021) Chassis No: MH3SG5680MK094860

Colour: Odometer: 16526 km Black

**Engine Capacity:** 155 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 110/80 R17 Rear Tyre Size: 110/80 R17 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,586.00	2,914.50	2,671.50	47.82
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,100.00	330.00	770.00	70.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Cald	culated Gross Total (S\$)	6,686.00	3,244.50	3,441.50	51.47
Approved	Total (Overridden) (S\$)		2,600.00		
	(S\$)	6,686.00	2,600.00	4,086.00	61.11
	+ GST 7.00/7.00% (S\$)	468.02	182.00	286.02	61.11
	Nett Amount (S\$)	7,154.02	2,782.00	4,372.02	61.11

**INSPECTION** 

Date Inspected:

Date of Assignment: 18/05/2022

> Teamwork Garage Pte Ltd (HQ) 17/05/2022 Inspected At:

53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park

Singapore 408934

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

### Reference

Part Source: (Last Synchronised: 14 Jul 2022)

Parts: N/A YAMAHA NMAX155 155cc ABS CVT (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBT571P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET LH FAIRING (MAIN) }	Scratched	350.00 FL	*650.00 FL
2	1		*LH FAIRING (SMALL) }	Scratched	200.00 FL	*- FL
3	1		*LH FAIRING (MIDDLE) }	Scratched	200.00 FL	*- FL
4	1		*LH FAIRING (LOWER)	Scratched	200.00 FL	*- FL
5	1		*REAR LH FAIRING }	Scratched	300.00 FL	*- FL
6	1		*FRONT HEADLAMP	Cracked	400.00 FL	*400.00 FL
7	1		*SET FRONT HEADLAMP LOWER FAIRING	} Scratched	280.00 FL	*350.00 FL
8	1		*FRONT HEADLAMP UPPER FAIRING }	Distorted	280.00 FL	*- FL
9	2		*SIGNAL LAMP	Serviceable	240.00 FL	*- FL
10	2		*BRAKE LEVER	Scratched	180.00 FL	*120.00 FL
11	1		*WING MIRROR (2PCS)	Scratched (1Pc Only)	180.00 FL	*90.00 FL
12	1		*SET BALANCER	Necessary	150.00 FL	*70.00 FL
13	1		*FRONT FENDER	Repair	180.00 FL	*- FL
14	1		*FRONT FORK	Bent	630.00 FS	*70.00 FS
15	1		*HANDLE BAR	Dented	250.00 FL	*175.00 FL
16	1		*MAIN STAND	Scratched	100.00 FL	*100.00 FL
17	1		*SET RH FAIRING (MAIN) }	Scratched	350.00 FL	*650.00 FL
18	1		*RH FAIRING (SMALL) }	Scratched	200.00 FL	*-FL
19	1		*RH FAIRING (MIDDLE) }	Scratched	200.00 FL	*- FL
20	1		*RH FAIRING (LOWER) }	Scratched	200.00 FL	*-FL
21	1		*LH MIDDLE FAIRING (LONG) }	Scratched	0.00 FL	*- FL
22	1		*STICKERS	Necessary	100.00 FS	*50.00 FS
23	1		*BOX	Scratched	800.00 FS	*450.00 FS
24	1		*FORK OIL	Not Necessary	30.00 FS	*-FS
25	1		*FORK SEAL	Not Necessary	30.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	6,030.00	3,175.00
	- List Item Discount on L Items 10.00/10.00% (S\$)				444.00	260.50
				Total Parts (S\$)	5,586.00	2,914.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING SYSTEM	New	100.00	30.00
2	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	New	500.00	200.00
3	TO SPRAY FENDER, FAIRINGS AND AFFECTED AREAS	New	500.00	100.00
	Gross Labour Cost (S\$)		1,100.00	330.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >